



# Product Change Notification

## 105357 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 105357 - 01  
**Change Title:** LAD945GCZCS, PCN 105357-01, FYI,  
CORTEZ: FAB D TO E CONVERSION,  
BIOS 1616  
**Date of Publication:** July 27, 2005

## Type of Change Notification:

FYI - (For Your Information)

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Aug 04, 2005
---	--------------

## Description of Change to the Customer:

- 1: moved Q1F1 component outside the KO zone.
- 2: BIOS change to 1616.

## Customer Impact of Change and Recommended Action:

Customer may want to validate BIOS changes.  
This board change is not expected to cause a change to the Microsoft\* Windows\* operating system's software driver stack. These hardware changes are being thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers. UPSD is not recommending additional qualification of these changes received from Intel.

## Products Affected / Intel Ordering Codes:

### Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
LAD945GCZCS	869689	869689	D10307-401	D10307-501	D10310-401	D10310-501

## Reference Documents / Attachments:

**Document:** **Location #:**

## **PCN Revision History:**

<b>Date of Revision:</b>	<b>Revision Number:</b>	<b>Reason:</b>
July 27, 2005	00	Originally Published PCN
July 27, 2005	01	Change from an FFF to FYI