



Product Change Notification

103198 - 01

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2003. Third-party brands and names are the property of their respective owners.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash, Trillium is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 103198 - 01
Change Title: SR2300, PCN 103198-01, FYI, Class 2; PS Support Rivet Change; Front Panel Button Change; I/O Gasket Modification
Date of Publication: March 14, 2003

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

Date of First Availability of Post-Conversion Material:	Mar 28, 2003
--	--------------

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

Power Supply Support Rivet Change - Changing the rivets to swedges by adding notches to the rear wall of the chassis power supply bracket to insure a tight fit against the base of the chassis.

Front Panel Board Button & Switch Activation Change - Made improvements to the chassis sheet metal and the front panel bezel to eliminate the front panel for being activated when moving the USB connector or pushing on the chassis's front panel bezel.

Chassis Rear I/O Gasket Modifications - Modifications made to the I/O gasket to prevent interference with the USB port are due to catching or tearing off the gasket during installation.

Customer Impact of Change and Recommended Action:

Power Supply Support Rivet Change - Changing the rivets to swedges by adding notches to the rear wall of the chassis power supply bracket to insure a tight fit against the base of the chassis - Customer needs to be aware of the change; no impact to customer expected

Front Panel Board Button & Switch Activation Change - Made improvements to the chassis sheet metal and the front panel bezel to eliminate the front panel for being activated when moving the USB connector or pushing on the chassis's front panel bezel - Customer needs to be aware of the change; no impact to customer expected

Chassis Rear I/O Gasket Modifications - Modifications made to the I/O gasket to prevent interference with the USB port are due to catching or tearing off the gasket during installation - Customer needs to be aware of the change; no impact to customer expected

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
KSW	847547	847547	A81074-009	A81074-010		
KSW480	852393	852393	A88341-007	A88341-008		
KWSKU15	852282	852282	A88345-012	A88345-013		
SE7501WV2SKU02	853023	853023	C22264-004	C22264-005		
SWVSKU02	852380	852380	C12303-011	C12303-012		

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
March 13, 2003	00	Originally Published PCN
March 14, 2003	01	Updated clarification made to the description of changes