



# Product Change Notification

## 106899 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: <mailto:asmo.pcn@intel.com>

Asia Pacific Contact: <mailto:apacgccb@intel.com>

Europe Email: <mailto:eccb@intel.com>

Japan Email: <mailto:jccb.ijkk@intel.com>

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 106899 - 01  
**Change Title:** D975XBX2, PCN 106899-01, Product Material, BIOS Update, Reason for Revision: Correct the pre-change AA number for LAD975XBX2LKR.  
**Date of Publication:** October 27, 2006

## Key Characteristics of the Change:

Product Material

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Oct 31, 2006
---	--------------

## Description of Change to the Customer:

**Reason for Revision:** Change current AA number for LAD975XBX2LKR.

Updating the BIOS to revision 2214.

## Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition. Detailed BIOS release notes can be viewed from: <http://developer.intel.com/products/motherboard/d975xbx2/tools.htm>

The changes have been thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers.

## Products Affected / Intel Ordering Codes:

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change AA	Post-Change AA
LAD975XBX2LKR	884201	884201	D53347-401	D53347-402
BLKD975XBX2KR	885036	885036	D53350-502	D53350-503
BOXD975XBX2KR	885040	885040	D53350-502	D53350-503
S975XBX2	885414	885414	D66350-301	D66350-302

## PCN Revision History:

Date of Revision:	Revision Number:	Reason:
October 25, 2006	00	Originally Published PCN
October 27, 2006	01	Correct the pre-change AA number for LAD975XBX2LKR.