



Product Change Notification

107406 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107406 - 00
Change Title: Intel PRO/10GbE LR Server Adapter, PXLA8591LRG1P5 MM#857392 (Lakeway LR OEM Generic), PRO/10GbE SR Server Adapter, PXLA8591SRG1P5 MM#858966 (Lakeway SR OEM Generic), PRO/10GbE SR Server Adapter, PXLA8591SR MM#858385 (Lakeway SR Retail), and PRO/10GbE LR Server Adapter, PXLA83951LR MM#858389 (Lakeway LR Retail)

PCN 107406-00

Label , Software

Peoples Republic of China (PRC) Environmental Friendly Use Period (EFUP) Label, Recycle Label, Peoples Republic of China (PRC) Materials Declaration Flyer, Software Driver Update, Standardizing Product ID Label and Standardizing 3n1 Label Size

Date of Publication: April 4, 2007

Key Characteristics of the Change:

Label
Software

| Forecasted Key Milestones: | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|
| Intel PRO/10GbE LR Server Adapter, PXLA8591LRG1P5 MM#857392 (Lakeway LR OEM Generic), PRO/10GbE SR Server Adapter, PXLA8591SRG1P5 MM#858966 (Lakeway SR OEM Generic) | |
| Date Customer Must be Ready to Receive Post-Conversion Material: | March 30, 2007 |
| PRO/10GbE SR Server Adapter, PXLA8591SR MM#858385 (Lakeway SR Retail) | |
| Date Customer Must be Ready to Receive Post-Conversion Material: | April 6, 2007 |
| PRO/10GbE LR Server Adapter, PXLA8591LR MM#858389 (Lakeway LR Retail) | |
| Date Customer Must be Ready to Receive Post-Conversion Material: | April 30, 2007 |

Description of Change to the Customer:

As a technology leader, Intel is making several important enhancements to its Intel® PRO Network Adapters. Intel will be implementing these changes due to recent People Republic of China (PRC) regulatory requirements, and to standardize products.

The Intel PRO/10GbE LR Server Adapter, PXLA8591LRG1P5 MM#857392 (Lakeway LR OEM Generic), PRO/10GbE SR Server Adapter, PXLA8591SRG1P5 MM#858966, (Lakeway SR OEM Generic), PRO/10GbE SR Server Adapter, PXLA8591SR MM#858385 (Lakeway SR Retail) and PRO/10GbE LR Server Adapter, PXLA83951LR MM#858389 (Lakeway LR Retail) products, as shown in the Affected Products Table within this PCN notification, will undergo the following changes:

Intel will implement the following changes due to the Peoples Republic of China (PRC) RoHS Regulatory requirements:

Intel will add a PRC Environmental Friendly Use Period (EFUP) label on the Network Adapters:

- PRC requires this EFUP label for control of Pollution caused by Electronic Information Products.
- This EFUP label will be placed on the secondary side of the adapter, **as shown in the pictures below**, the EFUP label could be placed in a slightly different location based upon space constraints. This label will include a 10 year use period for all Desktop adapters, or a 20 year use period number for all Server adapters.
- The products shown in the Affected Products Table, within this PCN notification, will include this new EFUP label.

PRC EFUP 10 year label



PRC EFUP 20 year label



Intel will add a Recycle Label to all of the Networking Adapter cardboard boxes:

- Placement of this recycle label will vary based upon space constraints. **Recycle Label shown in the picture below.**
- All products shown in the Affected Products Table within this PCN notification will include this new Recycle Label.

Recycle Label
size 45.00mm x 45.00mm, black ink



Intel will insert a PRC Materials Declaration Flyer into the Networking Adapter product boxes:

- The PRC Materials Declaration Flyer contains a table, which informs the Chinese consumers that only lead (Pb) is found in the product at levels that exceed 1000 ppm at the homogeneous level. **Customers can locate the Materials Declaration Flyer from the Intel Network Connectivity Solutions site,** http://www.intel.com/network/connectivity/solutions/rohs_prod.htm
- The Materials Declaration Flyer will be placed into the OEM generic 20 pak SKUs only.
- The products shown in the Affected Products Table within this PCN notification will include this new Flyer.

Intel is implementing the following changes in order to standardize the Networking Adapter product lines:

Software Driver Update:

- Intel will update the software drivers for the **Retail** adapters only to include support for Windows Vista, as shown in the Affected Products Table within this PCN notification.
- **Customers can download these new drivers at;**
http://downloadcenter.intel.com/scripts-df-external/Support_Intel.aspx
or <http://www.intel.com/support/network/adapter/>
- Please see the release notes with the drivers for additional details.

Standardizing Product ID Label on all Networking Adapter Products:

- All adapter products will now include a new Product ID label on the secondary side of the adapter PB (printed board) and on the outside of the adapter Static Bag (for products which are packaged in a Static Bag). **Please see pictures below.**
- The Product ID label will no longer be placed on the Clamshell.
- The products shown in the Affected Products Table, within this PCN notification, will include the Product ID label placement change.

Picture of ID Label on the Secondary Side of the adapter (example only)




Picture of ID Label on Static Bag (example only)



Standardizing 3n1 Label Size:

- The 3n1 label, which is placed on the primary side of the adapter in the upper right hand corner, will change from either a Large label size of 2" x .25" or Small label size of 1" x .20" to a Medium label size of 1.2" x 0.20". This will not affect the label data in any way. **Please see picture below.**
- We recommend all customers enable their bar code scanners to Scanning Code 93 for the new Medium sized label.
- The products shown in the Affected Products Table, within this PCN notification, will include the new Medium 3n1 label size.

Picture of Large, Small and Med sized labels (example shows size of labels only, not exact placement)



As a result of all changes above, the PBA (Printed Board Assembly) and TA (Top Assembly) numbers will roll, as shown within the Affected Products Table within this PCN notification. The MM (Material Master) and PC (Product Code) will not change for the affected products.

Customer Impact of Change and Recommended Action:

- The implementation date for all changes, on each SKU, will occur via a staggered implementation approach.
- Customers should expect to receive mixed inventory on all products until current inventory levels are depleted.
- If customers require samples, please contact your local Intel Field Sales Representative.

Products Affected / Intel Ordering Codes:

| Product Name | Product Code | Affected MM# | Old TA# | New TA# | Old PBA# | New PBA# |
|-------------------------------------------------------|----------------|--------------|------------|------------|------------|------------|
| PRO/10GbE LR Server Adapter, (Lakeway LR OEM Generic) | PXLA8591LRG1P5 | 857392 | C58258-001 | C58258-002 | C54891-005 | C54891-006 |
| PRO/10GbE SR Server Adapter, (Lakeway SR OEM Generic) | PXLA8591SRG1P5 | 858966 | C58256-003 | C58256-004 | C72663-004 | C72663-005 |
| PRO/10GbE SR Server Adapter, (Lakeway SR Retail) | PXLA8591SR | 858385 | C58822-004 | C58822-005 | C54889-007 | C54889-008 |
| PRO/10GbE LR Server Adapter, (Lakeway LR Retail) | PXLA8591LR | 858389 | C58823-002 | C58823-003 | C72665-003 | C72665-004 |

| Product Name | Product Code | Affected MM# | Peoples Republic of China (PRC) Environmental Friendly Use Period (EFUP) label | Recycle Label | Peoples Republic of China (PRC) Materials Declaration Flyer |
|-------------------------------------------------------|----------------|--------------|--------------------------------------------------------------------------------|---------------|-------------------------------------------------------------|
| PRO/10GbE LR Server Adapter, (Lakeway LR OEM Generic) | PXLA8591LRG1P5 | 857392 | X | X | X |
| PRO/10GbE SR Server Adapter, (Lakeway SR OEM Generic) | PXLA8591SRG1P5 | 858966 | X | X | X |
| PRO/10GbE SR Server Adapter, (Lakeway SR Retail) | PXLA8591SR | 858385 | X | X | |
| PRO/10GbE LR Server Adapter, (Lakeway LR Retail) | PXLA8591LR | 858389 | X | X | |

| Product Name | Product Code | Affected MM# | Software Driver Update | Standardizing Product ID Label | Standardizing 3n1 Label |
|-------------------------------------------------------|----------------|--------------|------------------------|--------------------------------|-------------------------|
| PRO/10GbE LR Server Adapter, (Lakeway LR OEM Generic) | PXLA8591LRG1P5 | 857392 | | X | X |
| PRO/10GbE SR Server Adapter, (Lakeway SR OEM Generic) | PXLA8591SRG1P5 | 858966 | | X | X |
| PRO/10GbE SR Server Adapter, (Lakeway SR Retail) | PXLA8591SR | 858385 | X | X | X |
| PRO/10GbE LR Server Adapter, (Lakeway LR Retail) | PXLA8591LR | 858389 | X | X | X |

Reference Documents / Attachments:

Document:

Location #:

Materials Declaration Flyer

http://www.intel.com/network/connectivity/solutions/rohs_prod.htm

Software Driver Download Update

http://downloadcenter.intel.com/scripts-df-external/Support_Intel.aspx

or

<http://www.intel.com/support/network/adapter/>

PCN Revision History:

Date of Revision:

April 4, 2007

Revision Number:

PCN107406-00

Reason:

Originally Published PCN