



# Product Change Notification

## 105388 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANdesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 105388 - 00  
**Change Title:** D945GCZ, PCN 105388-00, FYI, CLASS 2:  
BIOS 1616 UPDATE  
**Date of Publication:** August 08, 2005

**Type of Change Notification:**  
FYI - (For Your Information)

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Aug 08, 2005
---	--------------

## Description of Change to the Customer:

This BIOS update resolves a lan and memory issue.

## Customer Impact of Change and Recommended Action:

Customer may want to validate BIOS changes.  
This board change is not expected to cause a change to the Microsoft\* Windows\* operating system's software driver stack. These hardware changes are being thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers. UPSD is not recommending additional qualification of these changes received from Intel.

## Products Affected / Intel Ordering Codes:

### Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BLKD945GCZLKR	869570	869570	C99567-302	C99567-303	C99568-302	C99568-303
BLKD945GCZLR	869576	869576	D10312-304	D10312-305	D10313-304	D10313-305
BOXD945GCZLKR	869569	869569	C99567-302	C99567-303	C99568-302	C99568-303
BOXD945GCZLR	869579	869579	D10312-304	D10312-305	D10313-304	D10313-305

## Reference Documents / Attachments:

**Document:** **Location #:**

## **PCN Revision History:**

**Date of Revision:**

August 8, 2005

**Revision Number:**

00

**Reason:**

Originally Published PCN