



# Product Change Notification

## 106501 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 106501 - 00  
**Change Title:** Intel NetStructure® Host Media Processing (HMP) Software Release 1.3 for Windows, PCN 106501-00, Product Discontinuance, Product Discontinuance caused by availability of new and improved releases  
**Date of Publication:** September 01, 2006

## Key Characteristics of the Change:

Product Discontinuance

## Forecasted Key Milestones:

<b>Last Product Discontinuance Order Date:</b>	Dec 31, 2007
<b>Last Product Discontinuance Shipment Date:</b>	Dec 31, 2007
<b>Technical Support Service Ends:</b>	Jul 01, 2008

## Description of Change to the Customer:

Discontinuance of Intel NetStructure® Host Media Processing (HMP) Software Release 1.3 for Windows. HMP adds major functionality and features to new major releases. Customers have a 30 month timeframe from the time of HMP 1.3's replacement, HMP 2.0, where they are still supported for customer enablement issues.

Host Media Processing (HMP) Software Release 2.0 for Windows was deployed in December of 2005. For upgrade details please visit the Intel Web site listed below.

## Customer Impact of Change and Recommended Action:

No Service Updates will be released after December 1, 2007.

End of Support of HMP 1.3 is July 1, 2008.

End of Support is defined as the date after which the following support services are no longer available:

- Telephone, email and web support for affected product(s)
  - Customers will be directed to migration product
- Active reproduction of customer-reported issues
- Installation and configuration support
- Technote and application note creation and maintenance
- Issue entry and tracking via issue management tool
- Defect entry. Fixes for unresolved defects will not be pursued nor released in Point or Service Packages, or in a product revision. All unresolved defects must be dispositioned by Intel with agreement from key stakeholders.
- Feature Request entry. All open Feature Requests must be dispositioned by Intel with notification to key stakeholders.

### **Migration Path**

Customers are requested to migrate to Host Media Processing (HMP)  
Software Release 2.0 for Windows.

[http://www.intel.com/design/telecom/products/software/hmp/8762/overview  
.htm](http://www.intel.com/design/telecom/products/software/hmp/8762/overview.htm)

Product Codes being retired are listed below.

Contact your sales representative for additional migration information  
and/or any issues you may have with this Product Discontinuance and End  
of Support Plan.

### **Products Affected / Intel Ordering Codes:**

#### **Products Table**

<b>Affected Product Code</b>	<b>Affected MM#</b>
DMIPS10C13W	871995
DMIPS10E13W	872057
DMIPS10F13W	872056
DMIPS10I13W	872050
DMIPS10R13W	872046
DMIPS10S13W	872047
DMIPS10V13W	872045
DMIPS10C13WHD	872053
DMIPS10E3WHD	872052
DMIPS10F3WHD	872055
DMIPS10I3WHD	872054
DMIPS10R3WHD	872051
DMIPS10S3WHD	872049
DMIPS10V3WHD	872048

### **Reference Documents / Attachments:**

**Document:**

**Location #:**

HMP 2.0

<http://www.intel.com/design/telecom/products/software/hmp/8762/overview.htm>

### **PCN Revision History:**

**Date of Revision:**

**Revision Number:**

**Reason:**

September 1, 2006

00

Originally Published PCN