



Product Change Notification

106856 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106856 - 02
Change Title: S5000PAL/S5000XAL, Class 1, PCN 106856-02, Product Design, BIOS/FW Update,
Reason for Revision: Updating SW versions
Date of Publication: November 01, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Nov 17, 2006
---	--------------

Description of Change to the Customer:

Reason for Revision: Updating SW versions

The system software programmed at the factory is being updated.

BIOS - From R59 to R66
BMC - From R53 to R55
FRUSDR - From R36 to R38

The system software updates, including release notes for each, is available for download from Intel's secure website IBL, and from Intel's support website:
<http://support.intel.com/support/motherboards/server/S5000PAL/>

Customer Impact of Change and Recommended Action:

Customers may want to perform re-qualification, re-test, re-certification or standard validation testing for this change.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
BB5000PAL	885477	D26897-801	D13607-801	887282	D26897-802	D13607-802
S5000PAL	885478	D51458-003	D13607-801	885478	D51458-004	D13607-802
BB5000XAL	885479	D49413-801	D46952-801	887283	D49413-802	D46952-802

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
October 9, 2006	00	Originally Published PCN
October 10, 2006	01	Updating TA#s
November 1, 2006	02	Updating SW versions