



Product Change Notification

107018 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107018 - 01
Change Title: DQ965GF, PCN 107018-01, Product Design, FAB SPIN TO FIX A COMPONENT ISSUE, ADD ADDITIONAL MATERIAL SUPPORT, Reason for Revision: Title name is incorrect
Date of Publication: January 11, 2007

Key Characteristics of the Change: Product Design

Forecasted Key Milestones:

Date of Samples Availability:	Dec 22, 2006
Date Customer Must be Ready to Receive Post-Conversion Material:	Nov 30, 2006

Description of Change to the Customer:

Reason for Revision: Title name is incorrect

AA/PBA# DASH+1 to fix a component issue
Update Software CD for Bulk/Box skus
Add additional materials for improved supply line

Customer Impact of Change and Recommended Action:

The changes have been thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Post Change AA
LADQ965GFKRA1 878118	878118	D41019-303	D41019-400
LADQ965GFKR 878120	878120	D41016-303	D41016-400
BLKDQ965GFEKR 878944	878944	D41676-305	D41676-400
BOXDQ965GFEKR 878946	878946	D41676-305	D41676-400

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
December 18, 2006	00	Originally Published PCN
January 11, 2007	01	Title name is incorrect

