



Product Change Notification

105794 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105794 - 00
Change Title: D955XBK & D955XCS, PCN 105794-00, FYI, LAN chip, LAN image, BIOS and Installer CD change
Date of Publication: February 05, 2006

Type of Change Notification:

FYI - (For Your Information)

Key Characteristics of the Change:

Product Material
Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Feb 16, 2006
---	--------------

Description of Change to the Customer:

The D955XBK and D955XCS desktop board is being:

1. Converted to alternate LAN chip.
2. Updated with new LAN image to support this conversion.
3. Updated with new revision of installer CD
4. Upgrade to latest BIOS revision P2015 in the coming shipment. The latest BIOS, and release notes are available at: ftp://aiedownload.intel.com/df-support/9599/ENG/BK_2015_ReleaseNotes.pdf

Customer Impact of Change and Recommended Action:

These board changes have been thoroughly evaluated to ensure that there are no quality, reliability or HW functional implications to our customers.

These changes ARE expected to affect the Microsoft* Windows* operating system's software driver stack, or software image stack due to a subsystem vendor ID change.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
-----------------------	----------------	-----------------	---------------------	----------------------	----------------	-----------------

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BLKD955XBKLKR 869540	869540	869540	C96732-500	C96732-501	C96733-500	C96733-501
BLKD955XCSLKR 869542	869542	869542	C93516-402	C93516-403	C93517-402 rev3	C93517-403
BOXD955XBKLKR 869543	869543	869543	C96732-500	C96732-501	C96733-500	C96733-501
BOXD955XCSLKR 869541	869541	869541	C93516-402	C93516-403	C93517-402 rev3	C93517-403

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

February 5, 2006

Revision Number:

00

Reason:

Originally Published PCN