



Product Change Notification

107043 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107043 - 00
Change Title: DQ965WC, PCN 107043-00, Product Material, Audio codec update
Date of Publication: November 29, 2006

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 12, 2007
---	--------------

Description of Change to the Customer:

Update the IDT STAC9227 audio codec to the latest revision for improved audio performance.

Customer Impact of Change and Recommended Action:

The pre-existing audio driver will re-enumerate automatically due to the Microsoft* Windows* Plug-and-Play* mechanism. The re-enumeration will impact existing operating system image. Customers with image built with previous codec will need to reboot to get the driver to work properly. This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. Intel is not recommending additional qualification of these changes on platforms.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Post Change AA
BOXDQ965WCEKR 878938	878938	D41834-500	TBD
BLKDQ965WCEKR 878939	878939	D41834-500	TBD
LADQ965WCKR 879459	879459	D39923-500	TBD

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

November 29, 2006

Revision Number:

00

Reason:

Originally Published PCN