



Product Change Notification

111131 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #:	111131 - 00
Change Title:	Intel Ethernet Server Adapters X520-DA2/SR1/SR2/LR1, EX520DA2G2P5/E10G42BTDA/E10G41BFSR/E10G41BFSRG1P5/E10G42BFSR/E10G42BFSRG1P5/E10G41BFLR (Spring Fountain DA2/SR1/SR2/LR1 OEM generic/Retail) PCN 111131-00 Label OUI block change
Date of Publication:	November 14, 2011

Key Characteristics of the Change:

Label

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Nov 29, 2011
---	--------------


Description of Change to the Customer:

The Intel Ethernet Server Adapters X520-DA2/SR1/SR2/LR1, EX520DA2G2P5/E10G42BTDA/E10G41BFSR/E10G41BFSRG1P5/E10G42BFSR/E10G42BFSRG1P5/E10G41BFLR (Spring Fountain DA2/SR1/SR2/LR1 OEM generic/Retail) will undergo the following changes:

OUI Block change: Past run rates have caused the available blocks of MAC addresses assigned to run out. The OUI Block 00-1B-21 has hit the low water mark, the new OUI Block will be 90-E2-BA.

As a result of this change, the PBA (printed board assembly) and TA (top assembly) numbers will roll as noted in the affected products table within this PCN notice. If the PBA/TA numbers are printed on any product or box labels, those will show the PBA/TA dash roll as well.

3n1 label change: The 3n1 label will change to reflect the new OUI Block number and PBA# dash roll (printed board assembly), as show in the picture below. The 3n1 label is placed on the Front side of the Printed Board. (picture example only)



Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

Customers can expect to receive mixed inventory until current inventory levels are depleted.

Products Affected / Intel Ordering Codes:

Product Name	Product Code	MM#	OLD TA	NEW TA	OLD PBA	NEW PBA
Intel Ethernet Server Adapter X520-DA2 Spring Fountain DA2 Retail	E10G42BTDA	900139	E68797-004	E68797-005	E68793-004	E68793-005
Intel Ethernet Server Adapter X520-DA2 Spring Fountain DA2 Open Optic OEM generic 5-pak	EX520DA2G2P5	913120	G24942-002	G24942-003	G24940-003	G24940-004
Intel Ethernet Server Adapter X520-SR1 Spring Fountain SR1 Retail	E10G41BFSR	900141	E68795-005	E68795-006	E68787-005	E68787-006
Intel Ethernet Server Adapter X520-SR1 Spring Fountain SR1 OEM generic 5-pak	E10G41BFSRG1P5	901222	E58748-004	E58748-005	E66593-006	E66593-007
Intel Ethernet Server Adapter X520-SR2 Spring Fountain SR2 Retail	E10G42BFSR	900137	E68788-005	E68788-006	E68785-005	E68785-006
Intel Ethernet Server Adapter X520-SR2 Spring Fountain SR2 OEM generic 5-pak	E10G42BFSRG1P5	901223	E58747-005	E58747-006	E70854-006	E70854-007
Intel Ethernet Server Adapter X520-LR1 Spring Fountain LR1 Retail	E10G41BFLR	900140	E65557-005	E65557-006	E66561-006	E66561-007

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
November 14, 2011	00	Originally Published PCN