



Product Change Notification

105307 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105307 - 01
Change Title: SR4850HW4, PCN 105307-01, FYI,
Class 1: BIOS, ROMB BIOS, PCI Card
Divider , P-Bay modification, and IRAM
Safety Label Update
Date of Publication: September 28, 2005

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Product Design
Software

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 09, 2005
Date of First Availability of Post-Conversion Material:	Aug 09, 2005

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

The following system level software and hardware updates will be implemented on the SR4850HW4 Server Platform:

1. System part rev from -002 to -003
2. Main board part rev from -602 to -603
 - BIOS change to BIOS P04
 - ROMB BIOS change to v514k
 - Change PLD from 4_0 to 4_1
 - Change PCIXCAP signal pull-up resistor (R7E17) value from 1.5K to 3.3K
3. P-bay modification to allow for 3.5" SAS & changing planar plate
4. IRAM mark added to safety label
5. Memory board installed in slot A rather than D
6. PCI Card Divider
 - PCI Card Divider C87459-002 set to alternate
 - PCI Card Divider C87459-003 set to preferred
 - PCI Card Divider interfered with some PCI cards

Customer Impact of Change and Recommended Action:

Customer should evaluate or qualify the system with the new components when available.

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SHW4UR	873092	874581	C92307-002	C92307-003	C92307-002	C92307-003

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

July 15, 2005

00

Originally Published PCN

September 28, 2005

01

Remove the Front Panel Board.
Add the PCI Card Divider .