



Product Change Notification

105911 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105911 - 00
Change Title: SE7320VP2, PCN 105911-00, Product Design, Class 2, Update Onboard Marvell NIC Controller SSID
Date of Publication: February 12, 2006

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

Date of First Availability of Post-Conversion Material:	Mar 10, 2006
--	--------------

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

The onboard Marvell NIC controller SSID is updating from 5012 to 3450.

Customer Impact of Change and Recommended Action:

Customers need to be aware of these changes and should evaluate the changes when available.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BVP7320	874905	874905	C77385-701	C77385-702	C63184-701	C63184-702
SC63184	867858	867858	C84466-701	C84466-702	C63184-701	C63184-702
SE7320VP2	867850	867850	C71271-007	C71271-008	C63184-701	C63184-702

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision: _____ **Revision Number:** _____ **Reason:** _____

