



# Product Change Notification

## 104977 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 104977 - 00  
**Change Title:** SR1400, PCN 104977-00, FYI, Class 2; iLCP Sub-Bezel improvement to Correct Bowing Issues  
**Date of Publication:** March 29, 2005

**Type of Change Notification:**  
FYI - (For Your Information)

**Key Characteristics of the Change:**  
Product Design

## Forecasted Key Milestones:

<b>Date of First Availability of Post-Conversion Material:</b>	Apr 22, 2005
--	--------------

*The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.*

## Description of Change to the Customer:

A change has been made to the Intel(R) Server Chassis SR1400 iLCP Sub-Bezel improvement to Correct Bowing Issues. The change will include adding 4 ribs inside the sub-bezel which will prevent the sub-bezel from bowing.

## Customer Impact of Change and Recommended Action:

Intel anticipates no customer impact for this change. Evaluate when available.

## Products Affected / Intel Ordering Codes:

### Component Product Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
ADWLCDBEZEL	857591	857591	C56644-001	C56644-002		

## Reference Documents / Attachments:

**Document:**

**Location #:**

## **PCN Revision History:**

**Date of Revision:**

March 29, 2005

**Revision Number:**

00

**Reason:**

Originally Published PCN