



Product Change Notification

105653 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105653 - 00
Change Title: SR4850HW4, FHW4UFRTPNL and FHW4UPRODUCT, PCN 105653-00, FYI, CLASS 2: Replace EOL USB hub, Change to lower processor air duct, Replace EOL DVD drive, Packaging change
Date of Publication: November 14, 2005

Type of Change Notification:

FYI - (For Your Information)

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date of First Availability of Post-Conversion Material:	Nov 07, 2005
--	--------------

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

SHW4UR

MM# 874581

Change the top assembly number from C92307-003 to C92307-004

Change the front panel board part number from C65075-300 to C65075-301
Replace the end of life (EOL) USB hub used on the front panel board

Change the chassis frame part number from C54427-006 to C54427-007
Change the lower air duct from part number from C80546-002 to C80546-003
C80546-002 lower air duct - alternate
C80546-003 lower air duct - preferred
The lower air duct has been changed to support hex nut heat sink screws. This change is a soft cut in. Customers may see both types of air ducts in system.

Change the option part number from C54930-003 to C54930-004
Replace DVD Rom Drive D12448-001 with D28361-001
EOL of current QSI/Philips SDR083 DVD combo drive; switch over to RoHS compliant SDR089

Add banding material around each individual system box before shipping and edge protectors.

FHW4UFRTPNL

MM# 870121

Change the top assembly number from C98642-001 to C98642-002

Change the front panel board part number from C65075-300 to C65075-301

Replace the end of life (EOL) USB hub used on the front panel board

FHW4UPRODUCT

871907

Change the top assembly part number from D17557-001 to D17557-002

Change the lower air duct from part number C80546-002 to C80546-003

C80546-003 lower air duct

The lower air duct has been changed to support hex nut heat sink screws.

Customer Impact of Change and Recommended Action:

Customer should evaluate or qualify the system with the new components when available.

The changes associated with this PCN were not cut in on a single date. Please use the following to identify which systems have all the changes implemented:

AZGR5450120 is the last serial number shipped for top assembly C92307-003.

AZGR5450130 is the first serial number shipped for top assembly C92307-004.

AZGR5460006 is the first serial number shipped for top assembly C92307-004 with all changes implemented

This PCN replaces the following PCNs:

105598-0x

105572-0x

105526-0x

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SHW4UR 874581	874581	NA	C92307-003	C92307-004		

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
FHW4UFRTPNL 870121	870121	NA	C98642-001	C98642-002	C65075-300	C65075-301
FHW4UPRODUCT 871907	871907	NA	D17557-001	D17557-002	C80546-002	C80546-003

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

November 14, 2005

Revision Number:

00

Reason:

Originally Published PCN