



# Product Change Notification

## 107295 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

Asia Pacific Contact: [apacgccb@intel.com](mailto:apacgccb@intel.com)

Europe Email: [eccb@intel.com](mailto:eccb@intel.com)

Japan Email: [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 107295 - 00  
**Change Title:** Intel NetStructure® Host Media Processing (HMP) Software Release for Windows and Linux, PCN 107295-00, Product Discontinuance, Product Discontinuance of software products to eliminate the current two-tier pricing based on system density  
**Date of Publication:** February 22, 2007

## Key Characteristics of the Change:

Product Discontinuance  
Product Marking

## Forecasted Key Milestones:

<b>Last Product Discontinuance Order Date:</b>	Mar 14, 2007
<b>Last Product Discontinuance Shipment Date:</b>	Mar 14, 2007

## Description of Change to the Customer:

Product Discontinuance of HMP high density products and elimination of the two tier pricing based on system density. There will no longer be low or high density options for each resource. We will offer a single option for each resource regardless of the number of ports per server. This will reduce a source of confusion with customers and reduce the complexity faced when upgrading systems.

The high density part numbers will be discontinued for all HMP lines, including Intel NetStructure® Host Media Processing Release 1.2 for Linux, Intel NetStructure® Host Media Processing Release 1.3 for Windows, Intel NetStructure® Host Media Processing Release 1.5 for Linux, Intel NetStructure® Host Media Processing Release 2.0 for Windows, and Intel NetStructure® Host Media Processing Release 3.0 for Windows.

In addition the 'low density' part numbers will be transitioned from Intel numbers to Dialogic numbers. The Intel and Dialogic part number cross reference are shown below.

## Customer Impact of Change and Recommended Action:

The 'high density' products will no longer be available for ordering after March 14, 2007. The 'low density' part numbers will continue to remain active and will be available for all supported densities. Please update your systems with the correct part numbers and determine your remaining demand for the affected products and place orders in accordance with the key milestones listed.

### Migration Path

Customers are requested to migrate to the new Dialogic part numbers in the table below.

## Intel/Dialogic Part Number Cross Reference

The following table shows the Intel Product Codes and MM#, the corresponding Dialogic Part numbers and product names currently used for high density and the Dialogic part numbers and product names that will be used going forward for all resources regardless of density.

Current Intel Product Code and Dialogic Product Name	Intel MM #	Current Dialogic Part Number	New Dialogic Part Name	New Dialogic Part Number
<b>HMP for Linux Version 1.2</b>				
DMIPS10C12LHD	867766	866-009-01	DMIPS10C12L	866-008-01
DMIPS10E12LHD	867768	866-010-01	DMIPS10E12L	865-962-01
DMIPS10F12LHD	867733	866-012-01	DMIPS10F12L	865-995-01
DMIPS10I12LHD	867870	866-013-01	DMIPS10I12L	866-019-01
DMIPS10R12LHD	867735	866-015-01	DMIPS10R12L	866-014-01
DMIPS10S12LHD	867739	866-020-01	DMIPS10S12L	866-016-01
DMIPS10V12LHD	867737	866-018-01	DMIPS10V12L	866-017-01
<b>HMP for Windows Version 1.3</b>				
DMIPS10C13WHD	872053	872-053-01	DMIPS10C13W	871-995-01
DMIPS10E13WHD	872052	872-052-01	DMIPS10E13W	872-057-01
DMIPS10F13WHD	872055	872-055-01	DMIPS10F13W	872-056-01
DMIPS10I13WHD	872054	872-054-01	DMIPS10I13W	872-050-01
DMIPS10R13WHD	872051	872-051-01	DMIPS10R13W	872-046-01
DMIPS10S13WHD	872049	872-049-01	DMIPS10S13W	872-047-01
DMIPS10V13WHD	872048	872-048-01	DMIPS10V13W	872-045-01
<b>HMP for Linux Version 1.5</b>				
DMIPS10C15LHD	875604	875-604-01	DMIPS10C15L	875-605-01
DMIPS10E15LHD	875691	875-691-01	DMIPS10E15L	875-641-01
DMIPS10F15LHD	877600	877-600-01	DMIPS10F15L	875-685-01
DMIPS10I15LHD	875669	875-669-01	DMIPS10I15L	875-675-01
DMIPS10R15LHD	875670	875-670-01	DMIPS10R15L	875-668-01
DMIPS10S15LHD	875666	875-666-01	DMIPS10S15L	875-667-01
DMIPS10V15LHD	875674	875-674-01	DMIPS10V15L	875-673-01
DMIPS10M15LHD	875734	875-734-01	DMIPS10M15L	875-733-01
Current Intel Product Code and Dialogic Product Name	Intel MM #	Current Dialogic Part Number	New Dialogic Part Name	New Dialogic Part Number
<b>HMP for Windows Version 2.0</b>				
DMIPS10C20WHD	878214	878-214-01	DMIPS10C20W	878-213-01
DMIPS10E20WHD	878216	878-216-01	DMIPS10E20W	878-215-01
DMIPS10F20WHD	878218	878-218-01	DMIPS10F20W	878-217-01
DMIPS10I20WHD	878220	878-220-01	DMIPS10I20W	878-219-01
DMIPS10R20WHD	878222	878-222-01	DMIPS10R20W	878-221-01
DMIPS10S20WHD	878224	878-224-01	DMIPS10S20W	878-223-01
DMIPS10V20WHD	878226	878-226-01	DMIPS10V20W	878-225-01
DMIPS10A20WHD	878212	878-212-01	DMIPS10A20W	878-198-01
<b>HMP for Windows Version 2.0 Upgrade</b>				
DMIPS10C20WHDUP	878272	878-272-01	DMIPS10C20WUP	878-271-01
DMIPS10E20WHDUP	878274	878-274-01	DMIPS10E20WUP	878-273-01
DMIPS10F20WHDUP	878277	878-277-01	DMIPS10F20WUP	878-276-01
DMIPS10I20WHDUP	878280	878-280-01	DMIPS10I20WUP	878-279-01
DMIPS10R20WHDUP	878285	878-285-01	DMIPS10R20WUP	878-284-01
DMIPS10S20WHDUP	878287	878-287-01	DMIPS10S20WUP	878-286-01
DMIPS10V20WHDUP	878293	878-293-01	DMIPS10V20WUP	878-292-01
Current Intel Product Code and Dialogic Product Name	Intel MM #	Current Dialogic Part Number	New Dialogic Part Name	New Dialogic Part Number
<b>HMP for Windows Version 3.0</b>				
DMIPS10C30WHD	886210	886-210-01	DMIPS10C30W	886-211-01
DMIPS10E30WHD	886208	886-208-01	DMIPS10E30W	886-209-01

DMIPS10F30WHD	886206	886-206-01	DMIPS10F30W	886-207-01
DMIPS10I30WHD	886204	886-204-01	DMIPS10I30W	886-205-01
DMIPS10R30WHD	886199	886-199-01	DMIPS10R30W	886-201-01
DMIPS10S30WHD	886198	886-198-01	DMIPS10S30W	886-200-01
DMIPS10M30WHD	886202	886-202-01	DMIPS10M30W	886-203-01
DMIPS10V30WHD	886247	886-247-01	DMIPS10V30W	886-197-01
<b>HMP for Windows Version 3.0 Upgrade</b>				
DMIPS10C30WHDUP	886273	886-273-01	DMIPS10C30WUP	886-271-01
DMIPS10E30WHDUP	886272	886-272-01	DMIPS10E30WUP	886-268-01
DMIPS10F30WHDUP	886274	886-274-01	DMIPS10F30WUP	886-266-01
DMIPS10I30WHDUP	886477	886-477-01	DMIPS10I30WUP	886-260-01
DMIPS10R30WHDUP	886250	886-250-01	DMIPS10R30WUP	886-258-01
DMIPS10S30WHDUP	886480	886-480-01	DMIPS10S30WUP	886-257-01
DMIPS10V30WHDUP	886404	886-404-01	DMIPS10V30WUP	886-252-01

Product Codes being retired are listed below.

Contact your sales representative for additional migration information and/or any issues you may have with this Product Discontinuance Plan.

### Products Affected / Intel Ordering Codes:

Affected Product Code	Affected MM#
DMIPS10C12LHD	867766
DMIPS10E12LHD	867768
DMIPS10F12LHD	867733
DMIPS10I12LHD	867870
DMIPS10R12LHD	867735
DMIPS10S12LHD	867739
DMIPS10V12LHD	867737
DMIPS10C13WHD	872053
DMIPS10E13WHD	872052
DMIPS10F13WHD	872055
DMIPS10I13WHD	872054
DMIPS10R13WHD	872051
DMIPS10S13WHD	872049
DMIPS10V13WHD	872048
DMIPS10C15LHD	875604
DMIPS10E15LHD	875691
DMIPS10F15LHD	877600
DMIPS10I15LHD	875669
DMIPS10M15LHD	875734
DMIPS10R15LHD	875670
DMIPS10S15LHD	875666
DMIPS10V15LHD	875674
DMIPS10A20WHD	878212
DMIPS10C20WHD	878214
DMIPS10E20WHD	878216
DMIPS10F20WHD	878218
DMIPS10I20WHD	878220
DMIPS10R20WHD	878222
DMIPS10S20WHD	878224
DMIPS10V20WHD	878226

DMIPS10C20WHDUP	878272
DMIPS10E20WHDUP	878274
DMIPS10F20WHDUP	878277
DMIPS10I20WHDUP	878280
DMIPS10R20WHDUP	878285
DMIPS10S20WHDUP	878287
DMIPS10V20WHDUP	878293
DMIPS10C30WHD	886210
DMIPS10E30WHD	886208
DMIPS10F30WHD	886206
DMIPS10I30WHD	886204
DMIPS10M30WHD	886202
DMIPS10R30WHD	886199
DMIPS10S30WHD	886198
DMIPS10V30WHD	886247
DMIPS10C30WHDUP	886273
DMIPS10E30WHDUP	886272
DMIPS10F30WHDUP	886274
DMIPS10I30WHDUP	886477
DMIPS10R30WHDUP	886250
DMIPS10S30WHDUP	886480
DMIPS10V30WHDUP	886404

**Reference Documents / Attachments:**

**Document:** \_\_\_\_\_ **Location #:** \_\_\_\_\_

**PCN Revision History:**

<b>Date of Revision:</b>	<b>Revision Number:</b>	<b>Reason:</b>
February 22, 2007	00	Originally Published PCN