



Product Change Notification

108200 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108200 - 01
Change Title: DG33TL, PCN 108200-01, Product Design, BIOS update for Yorkfield CPU support and implement enhanced features, Reason for Revision: BIOS version change
Date of Publication: April 01, 2008

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

| | |
|---|--------------|
| Date Customer Must be Ready to Receive Post-Conversion Material: | Apr 17, 2008 |
|---|--------------|

Description of Change to the Customer:

Reason for Revision: BIOS version change

Update BIOS to DPP3510J.86A.0413.2008.0306.2218
Please refer to the release notes posted at <http://developer.intel.com/products/motherboard/DG33TL/tools.htm>
BIOS will have the default SATA mode set to IDE instead of RAID, as in previous versions (within BIOS under "Advanced > Drive This Configuration > Configure SATA as IDE").
The BIOS will incorporate the Intel® Rapid Recover Technology.

Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition.

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. Intel is not recommending additional qualification of these changes on platforms received from Intel. This change is not expected to cause a change to the Microsoft* Windows* operating system's software driver stack.

There is no expected OS image change. However, system integrators who have built their OS image with RAID will need to change the BIOS setting (within BIOS under "Advanced > Drive Configuration > Configure SATA as") from IDE back to RAID before loading the image in their production line otherwise the image will fail. Intel recommends

customers to use the Intel® Integrator Toolkit (iTK) to perform this task automatically. Please refer to <http://www.intel.com/go/itk> for more details on iTK.

Products Affected / Intel Ordering Codes:

| Product Code | MM# | Pre Change AA | Post Change AA |
|---------------------|------------|----------------------|-----------------------|
| BLKDG33TLM | 890277 | D89517-803 | D89517-804 |
| BOXDG33TLM | 890280 | D89517-803 | D89517-804 |

PCN Revision History:

| Date of Revision: | Revision Number: | Reason: |
|--------------------------|-------------------------|--------------------------|
| March 10, 2008 | 00 | Originally Published PCN |
| April 1, 2008 | 01 | BIOS version change |