



# Product Change Notification

## 105912 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 105912 - 00  
**Change Title:** SE7320VP2D2, PCN 105912-00, Product Design, Update Onboard Marvell NIC Controller SSID  
**Date of Publication:** February 12, 2006

**Key Characteristics of the Change:**  
Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Mar 10, 2006
---	--------------

## Description of Change to the Customer:

The onboard Marvell NIC controller SSID is updating from 5012 to 3466

## Customer Impact of Change and Recommended Action:

Customers need to be aware of these changes and should evaluate the changes when available.

## Products Affected / Intel Ordering Codes:

### Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BVP7320D2	870645	870645	D11797-202	D11797-203	D10582-202	D10582-203
SD10582	871591	871591	D17250-202	D17250-203	D10582-202	D10582-203
SE7320VP2D2	873804	873804	D11440-004	D11440-005	D10582-202	D10582-203

## Reference Documents / Attachments:

**Document:** \_\_\_\_\_ **Location #:** \_\_\_\_\_

## PCN Revision History:

**Date of Revision:** February 12, 2006      **Revision Number:** 00      **Reason:** Originally Published PCN