



# Product Change Notification

**Change Notification #:** 119640-00

**Change Title:** Intel® Ethernet SFP28 SR Optic,  
PCN 119640-00, Product Design, Label,  
Manufacturing Site,  
Update to External Housing and Adding Supplier

**Date of Publication:** August 03, 2023

## Key Characteristics of the Change:

Product Design, Label, Manufacturing Site

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material</b>	October 20, 2023
--	------------------


## Description of Change to the Customer:

The Intel® SKU listed in the products affected table below will have the following change(s):


To ensure continued production and uninterrupted supply of the Intel® Ethernet SFP28 SR Optics modules, the following changes have been made.

1. The original supplier is adding a manufacturing site in Thailand resulting in a change to the manufacturer's part number. The new MFG P/N that will be printed on the label is LTF8505-BE-IN1. The parts manufactured at the new site will also incorporate an updated external optical housing latch to improve locking and unlocking, removal of the bottom side cover and screw and an increased bottom side label groove for label placement.


### a. Latch Change



b. Cover and Screw Removed




c. Label groove increased



2. Intel has also qualified a 2nd source in Malaysia. The MFG P/N printed on the label from this source will be FTLF8536P5BNL-IT.

The optics modules and product labels are pictured below.



All parts have been validated to the IEEE 802.3 Ethernet Specification and have been fully tested and passed the Intel qualification process for use on Intel branded network adapter products.

As a result of these changes above the TA (top assembly) number will roll as noted in the affected products table within this PCN notice. If the TA numbers are printed on any product or box labels, those will show the TA dash roll as well.

### **Customer Impact of Change and Recommended Action:**

Intel anticipates no impact to customers, however customers should be aware of the changes and take appropriate actions to accommodate the changes and avoid impact to their processes for receiving or integration in their factories.

Customers can expect to receive mixed inventory.

Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

### **Products Affected/Intel Ordering Codes:**

<b>Marketing Name</b>	<b>Product Code</b>	<b>MM#</b>	<b>Pre Change TA</b>	<b>Post Change MM</b>	<b>Post Change TA</b>
Intel® Ethernet SFP28 SR Optic	E25GSFP28SRX	958873	J82013-001	958873	J82013-002

### **PCN Revision History:**

**Date of Revision:**

August 03, 2023

**Revision Number:**

00

**Reason:**

Originally Published PCN



# Product Change Notification

## 119640-00

### Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at [www.intc.com](http://www.intc.com).

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)