



# Product Change Notification

**Change Notification #:** 119367-00

**Change Title:** Intel® Server System R2208WFTZSR, PCN 119367-00, Product Design, Label, Power Supply and Label Update

**Date of Publication:** November 30, 2022

## Key Characteristics of the Change:

Product Design, Label

## Forecasted Key Milestones:

<b>Customer Must be Ready to Receive Post-Conversion Material *</b>	December 15, 2022
---	-------------------

\* Intel appreciates the customer's desire to receive the latest revision of products. However, Intel manages inventory on a first in first out (FIFO) basis at the MM# level. Subsequently, customer requests for a specific revision of material (below the MM#) will not be supported by Intel.


## Description of Change to the Customer:

Intel is implementing the following changes on the item listed in the "Products Affected" table.

- Adding the UKCA logo in the Server Board Serial Number Label
- The 1300W Power supply is changing from H79286-011 to H79286-012 due to a firmware upgrade from 26.5.128 to 29.5.128 and a minor hardware change, there is no impact on functionality

## Power Supply Label

Before	After
<p>The label shows technical specifications for a switching power supply, including input/output ranges, power ratings, and safety warnings. The model number H79286-011 is highlighted in red. The UKCA logo is present in the bottom right corner.</p>	<p>The label is identical to the previous one but with the model number updated to H79286-012. The UKCA logo remains in the bottom right corner.</p>

**Board Label****Customer Impact of Change and Recommended Action:**

Intel anticipates no impact to customers. Please contact your local Intel Field Sales Representative if you have any further questions about these changes.

**Products Affected/Intel Ordering Codes:**

Marketing Name	Product Code	MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
Intel® Server System R2208WFTZSR, Single	R2208WFTZSR	986049	K39991-016	H48104-961	K39991-017	H48104-962
				H48104-951		H48104-952
				M71494-951		M71494-952
				M71494-961		M71494-962

**PCN Revision History:****Date of Revision:**

November 30, 2022

**Revision Number:**

00

**Reason:**

Originally Published PCN



# Product Change Notification

## 119367-00

### Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at [www.intc.com](http://www.intc.com).

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)