



Product Change Notification

109079 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109079 - 02
Change Title: Intel(R) Server Board S5000PSL, PCN 109079-02, Product Material, BIOS Update, Intel(R) System Management Software DVD Update, and Attention Doc Update, Reason for Revision: SMS3.1 change and projected date change
Date of Publication: February 09, 2009

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 20, 2009
-------------------------------------------------------------------------	--------------

Description of Change to the Customer:

Reason for Revision: SMS3.1 change and projected date change

Intel is implementing the following changes:

- (1) Updating the board BIOS to version R0096. This updated BIOS release includes fixes for the Machine Check Exception (MCE) issue reported on a relatively small number of S5000PSL baseboards when using some Intel(R) Xeon(R) 5400 Series Processors.
- (2) Updating the Intel(R) System Management Software DVD to SMS3.1
- (3) Updating the board's attention document

Customer Impact of Change and Recommended Action:

Intel recommends all customers update their board BIOS to the latest version as soon as possible to prevent recurrence of any MCE related issues. Customers can check the latest software package at <http://support.intel.com/support/motherboards/server/s5000psl/>

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
S5000PSLSATAR	900323	E12274-004	E11027-301	901762	E12274-005	E11027-302
S5000PSLROMBR	900325	E12273-004	E11027-301	901763	E12273-005	E11027-302
S5000PSLSASR	900330	E12267-301	E11025-301	901764	E12267-302	E11025-302

BB5000PSLSATAR	900458	E12382-301	E11027-301	901721	E12382-302	E11027-302
BB5000PSLSASR	900528	E12378-301	E11025-301	901720	E12378-302	E11025-302
BB5000PSLROMBR	900529	E12374-004	E11027-301	901719	E12374-005	E11027-302
SE11025	900530	E20906-301	E11025-301	901724	E20906-302	E11025-302
BB5000XSLSATAR	900534	E12387-201	E11032-201	901723	E12387-202	E11032-202

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
December 3, 2008	00	Originally Published PCN
December 11, 2008	01	Update MM# for BB5000PSLROMBR
February 9, 2009	02	SMS3.1 change and projected date change