



Product Change Notification

106974 - 03

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106974 - 03
Change Title: S3000PT, PCN 106974-03, Product Design, Class1 Change SIO to SCH5027D, update BIOS to R37 and one resistor change for customer front pannel power LED issue and Adding California perchlorate documentation for all SKUs, Reason for Revision: BIOS version change
Date of Publication: December 20, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 08, 2007
---	--------------

Description of Change to the Customer:

Reason for Revision: BIOS version change

Update SIO from SCH5017D to SCH5027D. Update BIOS to R37 for quad-core processor support and one resistor change for customer front pannel power LED issue and Adding California perchlorate documentation.

Customer Impact of Change and Recommended Action:

Orders for post-change product need to be placed using the new MM #.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change Product Code	Post Change MM#	Post Change TA	Post Change PBA
BPTHBB 885342	885342	D67881-204	D60097-204	BPTHBB	888000	D67881-205	D60097-205
BPTVBB 885343	885343	D67882-204	D60098-204	BPVBB	888001	D67882-205	D60098-205
S3000PTH 885344	885344	D72613-204	D60097-204	S3000PTH	888003	D72613-205	D60097-205

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
November 8, 2006	00	Originally Published PCN
December 10, 2006	01	Change the BIOS vesion and one resistor change for customer front pannel power LED issue
December 18, 2006	02	Adding California perchlorate documentation
December 20, 2006	03	BIOS version change