



Product Change Notification

106278 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106278 - 00
Change Title: SS7 Software License Buttons SS7SBPCIxxx, PCN 106278-00, Product Discontinuance, Product Discontinuance of transaction based and NUP protocol license buttons caused by consolidation of license button offerings
Date of Publication: May 18, 2006

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Orders are Non-Cancelable and Non-Returnable After:	Jul 15, 2006
Last Product Discontinuance Order Date:	Aug 19, 2006
Last Product Discontinuance Shipment Date:	Sep 23, 2006
Last Product Return Date:	Jul 15, 2006
Technical Support Service Ends:	Aug 18, 2007

Description of Change to the Customer:

Discontinuance of the transaction based and NUP SS7 protocol license buttons for the entry level, high-value Intel NetStructure® SS7SPCI4 and SS7SPCI2S signaling boards. These discontinued license button have low sales volumes and are not planned to be converted to RoHS compliant.

Note: The remaining license buttons for the entry-level, high-value SS7SPCIxx cards will be converted to RoHS compliant versions. Those buttons are the ones that enable on-board MTP2, MTP3, ISUP, TUP, or the monitoring mode.

Customer Impact of Change and Recommended Action:

Please determine your remaining demand for the affected product and place orders in accordance with the key milestones listed.

Note: By law, the discontinued license buttons, that are not RoHS compliant may not be shipped to EMEA customers after 30 June 2006.

Migration Plan

Product being Discontinued	Migration product	Migration Issues
SS7SBPCIIS41	HD: SS7HDPD4TEW + SS7SBHDFBEQ LD: SS7SBPCIMTPQ + Host based protocols (SS7SBHSTSCCPCL + SS7SBHSTTCAP + SS7SBHSTIS41)	None
SS7SBPCIISTC	HD: SS7HDPD4TEW + SS7SBHDFBDQ LD: SS7SBPCIMTPQ + Host based protocols	None

	(SS7SBHSTSCCPCL + SS7SBHSTTCAP + SS7SBHSTISUP)	
SS7SBPCIMAP	HD: SS7HDPD4TEW + SS7SBHDFBEQ LD: SS7SBPCIMTPQ + Host based protocols (SS7SBHSTSCCPCL + SS7SBHSTTCAP + SS7SBHSTMAP)	None
SS7SBPCISCCPCL	HD: SS7HDPD4TEW + SS7SBHDFBDQ LD: SS7SBPCIMTPQ + Host based protocols (SS7SBHSTSCCPCL)	None
SS7SBPCITCAP	HD: SS7HDPD4TEW + SS7SBHDFBDQ LD: SS7SBPCIMTPQ + Host based protocols (SS7SBHSTSCCPCL + SS7SBHSTTCAP)	None
SS7SBPCISCCPCO	HD: SS7HDPD4TEW + SS7SBHDFBDQ LD: SS7SBPCIMTPQ + Host based protocols (SS7SBHSTSCPCO)	None
SS7SBPCINUP	No direct replacement. (Obsolete protocol). Migrate to ISUP. SS7SBPCIISTUPQ	None
SS7SBPCINUPL	No direct replacement. (Obsolete protocol). Migrate to ISUP. SS7SBPCIISTUPLQ	None

Contact your sales representative for additional migration information and/or any issues you may have with this Product Discontinuance Plan.

Products Affected / Intel Ordering Codes:

License Button Table

Affected Product Code	Affected MM#
SS7SBPCIS41	842690
SS7SBPCIISTC	842691
SS7SBPCIMAP	842689
SS7SBPCISCCPCL	842686
SS7SBPCITCAP	842688
SS7SBPCISCCPCO	842687
SS7SBPCINUP	842684
SS7SBPCINUPL	842685

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

May 18, 2006

00

Originally Published PCN