



Product Change Notification

111176 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #:	111176 - 00
Change Title:	Intel PRO/1000 MF Dual Port Server Adapters (Double Eldridge OEM generic/Retail), PRO/1000 PF Server Adapters (Sheepshead Bay OEM generic/Retail) and PRO/1000 PF Dual Port Server Adapters (Bretona OEM generic/Retail) PCN 111176-00 Label OUI block change
Date of Publication:	December 2, 2011

Key Characteristics of the Change:

Label

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Dec 17, 2011
---	--------------


Description of Change to the Customer:

The Intel PRO/1000 MF Dual Port Server Adapters (Double Eldridge OEM generic/Retail), PRO/1000 PF Server Adapters (Sheepshead Bay OEM generic/Retail) and PRO/1000 PF Dual Port Server Adapters (Bretona OEM generic/Retail) will undergo the following changes:

OUI Block change: Past run rates have caused the available blocks of MAC addresses assigned to run out. The OUI Block 00-1B-21 has hit the low water mark, the new OUI Block will be 68-05-CA (Sheepshead Bay, Bretona) and 90-E2-BA (Double Eldridge).

As a result of this change, the PBA (printed board assembly) and TA (top assembly) numbers will roll as noted in the affected products table within this PCN notice. If the PBA/TA numbers are printed on any product or box labels, those will show the PBA/TA dash roll as well.

3n1 label change: The 3n1 label will change to reflect the new OUI Block number and PBA# dash roll (printed board assembly), as show in the picture below. The 3n1 label is placed on the Front side of the Printed Board. (picture example only)



Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

Customers can expect to receive mixed inventory until current inventory levels are depleted.

Products Affected / Intel Ordering Codes:

Product Name	Product Code	MM#	OLD TA	NEW TA	OLD PBA	NEW PBA
Intel PRO/1000 MF Dual Port Server Adapter (Double Eldridge Retail)	PWLA8492MF	844141	A85401-011	A85401-012	C41300-008	C41300-009
Intel PRO/1000 MF Dual Port Server Adapter (Double Eldridge Retail Blk 5-pak)	PWLA8492MFBLK5	847744	A85398-011	A85398-012	C41300-008	C41300-009
Intel PRO/1000 MF Dual Port Server Adapter (Double Eldridge OEM generic 20-pak)	PWLA8492MFG3P20	856117	C48913-007	C48913-008	C49735-007	C49735-008
PRO/1000 PF Server Adapter (Sheepshead Bay Retail)	EXPI9400PF	868976	C91160-008	C91160-009	D53758-006	D53758-007
PRO/1000 PF Server Adapter (Sheepshead Bay Retail Blk 5-pak)	EXPI9400PFBLK	868978	D16157-009	D16157-010	D53758-006	D53758-007
PRO/1000 PF Server Adapter (Sheepshead Bay OEM generic 20-pak)	EXPI9400PFG2P20	882023	D54170-008	D54170-009	D52006-009	D52006-010
PRO/1000 PF Dual Port Server Adapter (Bretona Retail)	EXPI9402PF	868974	C91156-009	C91156-010	D53756-007	D53756-008
PRO/1000 PF Dual Port Server Adapter (Bretona OEM Retail Blk 5-pak)	EXPI9402PFBLK	868975	D15946-009	D15946-010	D53756-007	D53756-008
PRO/1000 PF Dual Port Server Adapter (Bretona OEM generic 20-pak)	EXPI9402PFG2P20	882458	D54169-008	D54169-009	D51927-010	D51927-011

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
December 2, 2011	00	Originally Published PCN