



# Product Change Notification

## 107493 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 107493 - 01  
**Change Title:** S5000VSA, PCN 107493-01, Product Design, Class 1, Board PBA Change, BIOS Update, SIO Stepping Change, SAS 1064E Controller Change, QSG/Config Label/User Guide and Intel Server Essentials CD Changes.  
**Reason for Revision:** Most recent BIOS version is R0078.  
**Date of Publication:** May 22, 2007

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

|   |              |
|---|--------------|
| <b>Date Customer Must be Ready to Receive Post-Conversion Material:</b> | Jun 11, 2007 |
|---|--------------|

## Description of Change to the Customer:

**Reason for Revision:** Most recent BIOS version is R0078.

The Intel(R) Server Board S5000VSA PBA is changing from -715 to -716  
The Server Board BIOS Revision is changing from BIOS R0074 (Intel P/N: D54212-055) to BIOS R0078 (Intel P/N: D54212-064)  
The SIO Controller Stepping is Changing from Revision A3 to Revision A4  
The LSISAS1064E Controller is changing from Intel P/N: D13187-003 to Intel P/N: D13187-004 to include Non Command Queing (NCQ) Support.  
The SAK: is changing from Intel P/N: D61026-003 to Intel P/N: D61026-004  
The S5000VSA CD Combo Kit is changing from Intel P/N: D36615-005 to Intel P/N: D36615-006  
The Intel Deployment Assistant CD is changing from Intel P/N: D36614-005 to Intel P/N: D36614-006  
The Configuration Label is changing from Intel P/N: D36975-002 to Intel P/N: D36975-003  
The QSG is changing from Intel P/N: D36976-002 to Intel P/N: D36976-003

## Customer Impact of Change and Recommended Action:

No impact to customer is projected. However, standard validation at customer site is highly recommended

## Products Affected / Intel Ordering Codes:

| Pre Change Product Code | Pre Change MM# | Pre Change TA | Pre Change PBA | Post Change MM# | Post Change TA | Post Change PBA |
|-------------------------|----------------|---------------|----------------|-----------------|----------------|-----------------|
| S5000VSASAS             | 886310         | D57136-006    | D57587-715     | 886310          | D57136-007     | D57587-716      |
| S5000VSA4DIMM           | 885886         | D57134-008    | D52032-715     | 885886          | D57134-009     | D52032-716      |
| S5000VSASATA            | 885885         | D57139-008    | D29137-715     | 885885          | D57139-009     | D29137-716      |
| S5000VSASCSI            | 885888         | D57140-008    | D29137-715     | 885888          | D57140-009     | D29137-716      |
| BSA2SASBB               | 890680         | D57131-006    | D57587-715     | 891199          | D57131-007     | D57587-716      |
| BSA2VBB                 | 890678         | D60287-008    | D52032-715     | 891198          | D60287-009     | D52032-716      |
| BSA2BB                  | 890676         | D56803-008    | D29137-715     | 891196          | D56803-009     | D29137-716      |

## Reference Documents / Attachments:

Document:

Location #:

## PCN Revision History:

Date of Revision:

Revision Number:

Reason:

April 18, 2007

00

Originally Published PCN

May 22, 2007

01

Most recent BIOS version is R0078.