



Product Change Notification

106722 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106722 - 01
Change Title: SR1500ALSAS/AXXSASIOMOD, Class 2, PCN 106722-01, Product Design, Firmware Update, Reason for Revision: Updating TA numbers
Date of Publication: September 20, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Oct 13, 2006
---	--------------

Description of Change to the Customer:

Reason for Revision: Updating TA numbers

MPT LSI1068 Firmware being programmed at the factory is being updated to v01.15.20.

The firmware update, including release notes, is available for download from Intel's secure web site IBL, and from Intel's support website: <http://support.intel.com/support/motherboards/server/S5000PAL/>

Customer Impact of Change and Recommended Action:

Customers may want to perform re-qualification, re-test, re-certification or standard validation testing for this change

Products Affected / Intel Ordering Codes:

Affected Product Code	Pre Change MM#	Post Change MM#	Pre Change TA	Post Change TA	Pre Change Sub Assembly	Post Change Sub Assembly
AXXSASIOMOD	880517	880517	D43799-003	D43799-004	D29308-401	D29308-402
ASR1500SASBP	880524	880524	D47653-002	D47653-003	D29308-401	D29308-402
SR1500ALSAS	885481	885481	D47497-005	D47497-006	D29308-401	D29308-402
SR1500ALSASNA	885483	885483	D47497-005	D47497-006	D29308-401	D29308-402

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:

August 28, 2006

September 20, 2006

Revision Number:

00

01

Reason:

Originally Published PCN

Updating TA numbers