



Product Change Notification

111211 - 01

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #:	111211 - 01
Change Title:	Intel PRO/1000 MT Server Adapters, PWLA8490MT/MTBLK5 (Everson Retail) and Intel PRO/1000 GT Quad Port Server Adapters, PWLA8494GT/GTBLK/GTG1P20 (Kingsport 3 LF Retail/OEM generic) PCN 111211-01 Label OUI block change PCN revision, Customer Ready to Receive date change from Jan 19, 2011 to Jan 19, 2012.
Date of Publication:	December 27, 2011

Key Characteristics of the Change:
Label

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 19, 2012
---	--------------

Description of Change to the Customer:


PCN revision, Customer Ready to Receive date change from Jan 19, 2011 to Jan 19, 2012.

The Intel PRO/1000 MT Server Adapters, PWLA8490MT/MTBLK5 (Everson Retail) and Intel PRO/1000 GT Quad Port Server Adapters, PWLA8494GT/GTBLK/GTG1P20 (Kingsport 3 LF Retail/OEM generic) will undergo the following changes:

OUI Block change: Past run rates have caused the available blocks of MAC addresses assigned to run out. The OUI Block 00-1B-21 has hit the low water mark, the new OUI Block will be 90-E2-BA.

As a result of this change, the PBA (printed board assembly) and TA (top assembly) numbers will roll as noted in the affected products table within this PCN notice. If the PBA/TA numbers are printed on any product or box labels, those will show the PBA/TA dash roll as well.

3n1 label change: The 3n1 label will change to reflect the new OUI Block number and PBA# dash roll (printed board assembly), as show in the picture below. The 3n1 label is placed on the Front side of the Printed Board. (picture example only)



Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

Customers can expect to receive mixed inventory until current inventory levels are depleted.

Products Affected / Intel Ordering Codes:

Product Name	Product Code	MM#	OLD TA	NEW TA	OLD PBA	NEW PBA
Intel PRO/1000 MT Server Adapters (Everson Retail)	PWLA8490MT	845956	A85402-011	A85402-012	C36840-009	C36840-010
Intel PRO/1000 MT Server Adapters (Everson Retail Blk 5-pak)	PWLA8490MTBLK5	847742	A90837-010	A90837-011	C36840-009	C36840-010
Intel PRO/1000 GT Quad Port Server Adapter (Kingsport 3 LF OEM generic 20-pak)	PWLA8494GTG1P20	869708	C99072-008	C99072-009	D30273-008	D30273-009
Intel PRO/1000 GT Quad Port Server Adapter (Kingsport 3 LF Retail)	PWLA8494GT	869970	D12592-007	D12592-008	D35392-007	D35392-008
Intel PRO/1000 GT Quad Port Server Adapter (Kingsport 3 LF Retail Blk 5-pak)	PWLA8494GTBLK	869971	D12606-008	D12606-009	D35392-007	D35392-008

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
December 19, 2011	00	Originally Published PCN
December 27, 2011	01	PCN revision, Customer Ready to Receive date change from Jan 19, 2011 to Jan 19, 2012.