



# Product Change Notification

## 106332 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 106332 - 00  
**Change Title:** D102GGC2, PCN 106332-00, Product Design, Update BIOS, remove product ID label, update EICD  
**Date of Publication:** May 15, 2006

**Key Characteristics of the Change:**  
Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	May 25, 2006
---	--------------

## Description of Change to the Customer:

1. Update BIOS to version GC11020M.86A.1065. Please refer to the product website at <http://www.intel.com/products/motherboard/d102ggc2> for the BIOS release notes. NOTE: This change will effectively remove RAID support on BOXD102GGC2L and BLKD102GGC2L
2. Remove product identifier label from motherboard
3. Update the Intel Express Installer CD to D49802-002 from D49802-001.

## Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. This change will however remove RAID support from BOXD102GGC2L and BLKD102GGC2L. Please ensure that your OS images have been updated to remove RAID support for those skus. The LAD102GGC2L is not affected by this change.

## Products Affected / Intel Ordering Codes:

### Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change AA	Post-Change AA
BLKD102GGC2L 880257	880257	880257	D42789-201	D42789-202
BOXD102GGC2L 880258	880258	880258	D42789-201	D42789-202
LAD102GGC2L 879092	879092	879092	D42788-201	D42788-202

**Reference Documents / Attachments:**

**Document:**

**Location #:**

**PCN Revision History:**

**Date of Revision:**

May 15, 2006

**Revision Number:**

00

**Reason:**

Originally Published PCN