



Product Change Notification

105434 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANdesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105434 - 00
Change Title: D945GCZ, PCN 105434-00, FYI, CLASS 2:
FAB C TO E BOM CONVERSION
Date of Publication: August 22, 2005

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 26, 2005
---	--------------

Description of Change to the Customer:

- 1: FET was moved to correct chassis interference.
- 2: Front panel header was replaced with one that is colored.
- 3: Lowered the BID to 1Kohm and changed the 1-Watt circuitry to 0ohm and 2.2K.
- 4: MCH part anchor and clip has been replaced with new part for the MCH heat sink on BTX.

Customer Impact of Change and Recommended Action:

This board change is not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. These hardware changes are being thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers. UPSD is not recommending additional qualification of these changes received from Intel.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BLKD945GCZLKR	869570	869570	C99567-303	C99567-501	C99568-303	C99568-501
BLKD945GCZLR	869576	869576	D10312-305	D10312-501	D10313-305	D10313-501
BOXD945GCZLKR	869569	869569	C99567-303	C99567-501	C99568-303	C99568-501
BOXD945GCZLR	869579	869579	D10312-305	D10312-501	D10313-305	D10313-501

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

August 22, 2005

Revision Number:

00

Reason:

Originally Published PCN