



Product Change Notification

109041 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109041 - 00
Change Title: S5000VSA, PCN 109041-00, Product Material, BIOS Update, Intel(R) System Management Software DVD Removal, and Attention Doc Update
Date of Publication: November 21, 2008

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 23, 2009
---	--------------

Description of Change to the Customer:

Intel is implementing the following changes:

- (1) Updating the board BIOS to version R0094 or later. This updated BIOS release includes fixes for the Machine Check Exception (MCE) issue reported on a relatively small number of S5000VSA baseboards when using some Intel(R) Xeon(R) 5400 Series Processors.
- (2) Removing the Intel(R) System Management Software DVD, and
- (3) Updating the board's attention document (E58651-001).

The board PBA's are also changing from -200 to -201:

SATA SKU	E11003-200 to E11003-201
4DIMM SKU	E11011-200 to E11011-201
SAS SKU	E11012-200 to E11012-201
SCSI SKU	E11003-200 to E11003-201

Customer Impact of Change and Recommended Action:

Intel recommends all customers update their board BIOS to the latest version as soon as possible to prevent recurrence of any MCE related issues.

Customers needing the Intel® Active System Console, Intel® Management Packs or any of the utilities found on the Intel® System Management Software DVD, can download them from <http://www.intel.com/go/servermanagement>.

Customers, who would like to evaluate Microsoft* System Center Essentials, can download it from <http://www.Microsoft.com/essentials>.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
S5000VSASATAR	900273	E10040-005	E11003-200	901745	E10040-006	E11003-201
S5000VSASCSIR	900317	E10041-005	E11003-200	901744	E10041-006	E11003-201
S5000VSASASR	900318	E10035-004	E11012-200	901746	E10035-005	E11012-201
S5000VSA4DIMMR	900319	E10009-004	E11011-200	901741	E10009-005	E11011-201
BSA2VBBR	900320	E10049-004	E11011-200	901743	E10049-005	E11011-201
BSA2BBR	900324	E10042-005	E11003-200	901742	E10042-006	E11003-201
BSA2SASBBR	900327	E10047-004	E11012-200	901747	E10047-005	E11012-201

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

November 21, 2008

00

Originally Published PCN