



Product Change Notification

108390 - 03

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108390 - 03
Change Title: SSR212MC2BR, SSR212MC2RBR ECO, PCN 108390-02, Product Material, STORAGE, ECO UPDATED FW/SW, DOCUMENTATION, AND BOARD SPIN.
Reason for Revision: Reason for Revision: Correct EM FW revision.
Date of Publication: July 30, 2008

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	July 28, 2008
---	---------------

Description of Change to the Customer:

Reason for Revision: Correct EM FW revision.

Updates include the following:

- 1) Quick Start Guide updated to D91284-003.
- 2) Attention Doc updated to D91601-005.
- 3) Resource CD updated to D91204-005.
- 4) S5000PSLSASR server board updated to E11025-102.
- 5) S5000PSLSASR server board BIOS updated to S5000.86B.10.00.0088.
- 6) S5000PSLSASR server board BMC FW updated to 00.63.
- 7) S5000PSLSASR server board FRUSDR FW updated to XYSL46.
- 8) RAID Controller SRCAS144E updated to FW 1.12.120-0394.
- 9) **Enclosure Management Card FW updated to 1.0.4-60.**
- 10) Storview® Enclosure Management Software updated to 3.07.008.
- 11) Introduce alternates for BBU cable, SMBus/reset/power cable, PSU harness cable sheathing.
- 12) Introduce alternate RAID Controller SRCAS144E revision, D53147-152.
- 13) Add RMM2 Low Profile I/O Bracket to accessory kit.
- 14) Lengthen front panel thumb screws by 3mm.
- 15) Improved Rail Kit blue plastic latch.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customer.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Post Change MM#	Pre Change TA	Post Change TA
SSR212MC2RBR	893519	893519	D88965-005	D88965-006
SSR212MC2BR	893628	893628	D88964-005	D88964-006
SSR212MC2RBRNA	894040	894040	D88965-005	D88965-006
SSR212MC2BRNA	894041	894041	D88964-005	D88964-006

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

April 8, 2008

00

Originally Published PCN

June 3, 2008

01

Availability date, FW/SW revision updates, several items added.

July 21, 2008

02

Change availability date, remove item 16.

July 30, 2008

03

Correct EM FW revision.