



Product Change Notification

107048 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107048 - 01
Change Title: S5000PAL and S5000PAL based systems, PCN 107048-01, Product Design, Updating the CD Combo Kit, Reason for Revision: Adding TA numbers
Date of Publication: December 28, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

| | |
|---|--------------|
| Date Customer Must be Ready to Receive Post-Conversion Material: | Jan 08, 2007 |
|---|--------------|

Description of Change to the Customer:

Reason for Revision: Adding TA numbers

The CD kit included in the listed products will be changing. There will be updates to the included RAID drivers, the Intel Deployment Assistant, and Intel Server Management. The Kit will be migrating from 2 disks to 3 disks in order to hold the extra content. The drivers, Intel Deployment Assistant, and Intel Server Management versions to be included in the kit are available for download from Intel's secure web site IBL, and from Intel's support web site:

<http://support.intel.com/support/motherboards/server/s5000pal/>

This change is implementing concurrently with PCNs #106864 and #106866

Customer Impact of Change and Recommended Action:

Intel does not foresee any adverse customer impact to these changes. Intel recommends performing a standard level of evaluation as updated product becomes available.

Products Affected / Intel Ordering Codes:

| Pre Change Product Code | Pre Change MM# | Pre Change TA | Post Change MM# | Post Change TA |
|-------------------------|----------------|---------------|-----------------|----------------|
| S5000PAL | 885478 | D51458-004 | 885478 | D51458-005 |
| SR1500AL | 885480 | D47500-007 | 885480 | D47500-008 |
| SR1500ALSAS | 885481 | D47497-008 | 885481 | D47497-009 |
| SR1550AL | 885484 | D50324-004 | 885484 | D50324-005 |
| SR1550ALSAS | 885485 | D50323-005 | 885485 | D50323-006 |
| SR2500ALBRP | 885488 | D43693-008 | 885488 | D43693-009 |
| SR2500ALLX | 885489 | D43690-010 | 885489 | D43690-011 |

| | | | | |
|---------------|--------|------------|--------|------------|
| SR1500ALNA | 885482 | D47500-007 | 885482 | D47500-008 |
| SR1500ALSASNA | 885483 | D47497-008 | 885483 | D47497-009 |
| SR2500ALBRPNA | 885498 | D43693-008 | 885498 | D43693-009 |
| SR2500ALLXNA | 885499 | D43690-010 | 885499 | D43690-011 |
| SR1550ALNA | 885486 | D50324-004 | 885486 | D50324-005 |
| SR1550ALSASNA | 885487 | D50323-005 | 885487 | D50323-006 |

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

November 30, 2006

00

Originally Published PCN

December 28, 2006

01

Adding TA numbers