



Product Change Notification

Change Notification #: 113519 - 02
Change Title: CAMERA MOD 82564IVCHVM
PCN 113519-02, Product Design, Label,
Transport Media
Firmware upgrade, **Label Update, and
Package Change,**
**Reason for Revision: Label and Package
Change Addendum**

Date of Publication: February 17, 2015

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 01, 2015
-------------------------------------------------------------------------	--------------

Description of Change to the Customer:

Reason for Revision: Label and Package Change Addendum

The Intel® CAMERA MOD 82564IVCHVM will undergo the following changes.

The new Firmware 2.50.0.0 will replace version 2.38.5.0 for features update and improved product performance.

Intel will begin shipment of modules with FW 2.50.00 and TA H53987-110 in March'15

Intel will stop shipping modules with FW 2.38.5.0 and TA H53987-100 Rev 3 **by the
2nd week of May'15 (WW 20)**

Label Change

The content of the QR label to include more information in both readable characters and QR content.

1. Label size will remain the same
2. First readable line - S/N
3. Second readable line - #MM (First 6 digits)#TA(last10 digits)

Example Label New













4. QR info will be changed to 28 digits number (No spaces) reflecting the following information:
 - a) 1-12 S/N
 - b) 13-18 #MM
 - c) 19-28 TA#
4. Example: 471400267-03933759H53987-100

Package Change

The Shipping container is being changed from an oversized box with cushioning material, to a dedicated box of reduced size and enhanced reliability which will also enable better support of Minimum Order Quantity,

Old	New
Dimensions 550mm x 389 x 360mm	Dimensions 460mm x 211mm x 196mm
	

Package labels will be changed as follows:

Old	New
<p>Intel® PerC IVCAM</p>   <p>Product Code: IDC_IVCAM_013 CartonID: A123456789</p> <p>U P C 7 358582 30865 E A N 5 032037 02564 5 MM#: 915876</p>   <p>Batch#: ABCDEFGHXX Qty: 300 Packdate: 09 APR 14</p> <p>Product inside is not labeled for individual resale</p> <p>Made in Thailand</p>	<p>Intel® PerC IVCAM</p>   <p>Product Code: IDC_IVCAM_013 CartonID: A123456789</p> <p>U P C 7 358582 30865 E A N 5 032037 02564 5 MM#: 915876</p>    <p>Batch#: ABCDEFGHXX Qty: 300 Firmware: 2.36.9.0</p> <p>Work Order: 02 FEB 15</p> <p>Product inside is not labeled for individual resale</p>  <p>Made in Thailand</p>

The Below table summarizes all the product combination related to the changes detailed above

FW	TA	Product label	Package
2.50.0.0	H53987-110	<p>NEW</p> 	<p>NEW</p>  

Customer Impact of Change and Recommended Action:

Intel will attempt to deplete pre-conversion material before shipping post-conversion material but there is a possibility of Intel shipping mixed inventory. Therefore, customers will need to manage both FWs in their manufacturing line and update the FW version, when needed, using the FW update tools.

The new firmware have been fully tested, qualified and approved by Intel. Intel anticipates no impact to customers on the HW side, and full compatibility with system configuration. However, on the SW side, this FW version is coupled with DCM1.3 and above.

Please contact your local Intel Field Sales representative if you have any further questions about this change.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change TA	Post Change TA
82564IVCHVM	933759	H53987-100 Rev 5	H53987-110

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
December 23, 2014	00	Originally Published PCN
January 6, 2015	01	Correct RTR Date typo in PDF
February 17, 2015	02	Label and Package Change Addendum