



Product Change Notification

110343 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2010. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 110343 - 02
Change Title: Intel® X18-M \ X25-M Solid-State Drive, PCN 110343-02, Product Design, Firmware version update from 02HD to 02M3, Reason for Revision: PCN Document attachment
Date of Publication: December 08, 2010

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 03, 2011
---	--------------

Description of Change to the Customer:

Reason for Revision: PCN Document attachment change

Intel is upgrading the firmware for its High Performance Solid-State MLC Drives (X25-M/X18-M) from 02HD to version 02M3. These changes are incremental improvements from previous firmware version. Inventory will transition in the Intel factory on or beyond the above date to replace older firmware version with the 02M3 version.

The changes to the TA and SA numbers are shown in the table below.

Please contact your Field Sales Personnel for Errata Report

Customer Impact of Change and Recommended Action:

Since this firmware update is considered incremental, Intel anticipates no product impact with this firmware, and re-qualification is not recommended.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change TA	Post Change TA	Pre Change SA	Post Change SA
SSDSA2MH160G2 901933	901933	E64371-310	E64371-311	E70560-310	E70560-311
SSDSA2MH080G2 901934	901934	E64370-310	E64370-311	E70559-310	E70559-311
SSDSA1MH160G2 901936	901936	E64369-310	E64369-311	E70557-310	E70557-311
SSDSA1MH080G2 901937	901937	E65912-310	E65912-311	E70556-310	E70556-311
SSDSA2MH080G2C 902211	902211	E92443-310	E92443-311	E64510-310	E64510-311

SSDSA2MH080G2C1902383	902383	E64508-310	E64508-311	E64510-310	E64510-311
SSDSA2MH160G2C1902384	902384	E64509-310	E64509-311	E64511-310	E64511-311
SSDSA2MH080G2R5902462	902462	E65910-311	E65910-312	E87240-203	E87240-204
SSDSA2MH160G2R5902464	902464	E65907-310	E65907-311	E64511-310	E64511-311
SSDSA1MH160G201903844	903844	E74780-310	E74780-311	E70557-310	E70557-311
SSDSA1MH080G201903845	903845	E74781-310	E74781-311	E70556-310	E70556-311
SSDSA2MH160G201903846	903846	E74784-310	E74784-311	E70560-310	E70560-311
SSDSA2MH080G201903847	903847	E74785-310	E74785-311	E70559-310	E70559-311
SSDSA2MH080G2IC904508	904508	E77932-310	E77932-311	E77935-310	E77935-311
SSDSA2MH080G2I 904509	904509	E77922-310	E77922-311	E77924-310	E77924-311
SSDSA1MH080G2I 904510	904510	E77885-310	E77885-311	E77898-310	E77898-311
SSDSA2MH160G2IC904511	904511	E77933-310	E77933-311	E77934-310	E77934-311
SSDSA2MH160G2I 904512	904512	E77923-310	E77923-311	E77927-310	E77927-311
SSDSA1MH160G2I 904513	904513	E77890-310	E77890-311	E77900-310	E77900-311
SSDSA2MP040G2C1904580	904580	E78153-311	E78153-312	E78155-311	E78155-312
SSDSA2MP040G2R5905205	905205	E83497-312	E83497-313	E87243-203	E87243-204
SSDSA2MJ080G2IC906037	906037	E87239-203	E87239-204	E87241-203	E87241-204
SSDSA2MJ080G2C1906056	906056	E87238-203	E87238-204	E87240-203	E87240-204
SSDSA2MJ080G201906102	906102	E87253-203	E87253-204	E75392-203	E75392-204
SSDSA2MJ080G2I 906301	906301	E87255-203	E87255-204	E90615-203	E90615-204
SSDSA2MQ040G2C1906574	906574	E87256-203	E87256-204	E87243-203	E87243-204
SSDSA2MJ080G2 908110	908110	E92951-203	E92951-204	E75392-203	E75392-204
SSDSA2MH080G2K5909118	909118	G11143-100	G11143-101	E87240-203	E87240-204
SSDSA2MH160G2K5909119	909119	G11144-100	G11144-101	E64511-310	E64511-311
SSDSA2MP040G2K5909120	909120	G11139-100	G11139-101	E87243-203	E87243-204
SSDSA2MH120G2K5910281	910281	G15693-103	G15693-104	G15695-103	G15695-104

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
December 4, 2010	00	Originally Published PCN
December 7, 2010	01	Post change TA# error for MM# 902462
December 8, 2010	02	PCN Document attachment