



Product Change Notification

106926 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106926 - 00
Change Title: SR4850HW4M,SR6850HW4M,SHW4URM3SA
and SHW6URM3SA, PCN 106926-00,
Manufacturing Site, Class 2: Accessories
FHWSATAIDE- board hole shape change
Date of Publication: November 07, 2006

Key Characteristics of the Change:

Manufacturing Site

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Dec 01, 2006
---	--------------

Description of Change to the Customer:

SR4850HW4M (SHW4URM)

Change the MM# from 877222 to 879454

Change top assembly part number from D35286-004 to D35286-005

Change SATA-IDE board part number from C71688-002 to C71688-003

SHW4URM3SA

Change the MM# from 881586 to 886995

Change top assembly part number from D46299-002 to D46299-003

Change SATA-IDE board part number from C71688-002 to C71688-003

SR6850HW4M (SHW6URM)

Change the MM# from 877219 to 879452

Change top assembly part number from D35289-002 to D35289-003

Change SATA-IDE board part number from C71688-002 to C71688-003

SHW6URM3SA

Change the MM# from 881402 to 887385

Change top assembly part number D46296-002 to D46296-003

Change SATA-IDE board part number from C71688-002 to C71688-003

FHWSATAIDE

MM 870273

Change top assembly part number D10881-002 to D10881-003

Change SATA-IDE board part number from C71688-002 to C71688-003

Change the J1 power connector PTH hole pattern change on SATA Bridge board to allow for better solder fill and flow.

Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

Products Affected / Intel Ordering Codes:

Affected Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
SHW4URM	877222	D35286-003	N/A	879454	D35286-004	N/A
SHW6URM	877219	D35289-002	N/A	879452	D35289-003	N/A
SHW6URM3SA	881402	D46296-002	N/A	887385	D46296-003	N/A
SHW4URM3SA	881586	D46299-002	N/A	886995	D46299-003	N/A
FHWSATAIDE	870273	D10881-002	C71688-002	870273	D10881-003	C71688-003

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

November 7, 2006

Revision Number:

00

Reason:

Originally Published PCN