



Product Change Notification

105253 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANdesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105253 - 00
Change Title: D915GMH, PCN 105253-00, FFF, CLASS 2 -
NEW CD, BIOS UPDATE & AUDIO
CODEC CONVERSION
Date of Publication: June 23, 2005

Type of Change Notification:
FFF - (Form-Fit-Function)

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jul 15, 2005
---	--------------

Description of Change to the Customer:

1. Update bios to version 0444 to support new audio CODEC
2. Use new audio codec to pass latest WHQL requirement
3. Incorporate New CDA for updated audio drivers

Customer Impact of Change and Recommended Action:

These board changes ARE expected to cause a change to the Microsoft* Windows* operating system's software driver stack due to a subsystem vendor ID change. These hardware changes have been thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BLKD915GMHL	860727	860727	C68829-204	C68829-205	C68834-204	C68834-205
BLKD915GMHLK	860726	860726	C68832-204	C68832-205	C68837-204	C68837-205
BOXD915GMHL	860731	860731	C68829-204	C68829-205	C68834-204	C68834-205
BOXD915GMHLK	860729	860729	C68832-204	C68832-205	C68837-204	C68837-205

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

June 23, 2005

Revision Number:

00

Reason:

Originally Published PCN