



Product Change Notification

107716 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107716 - 01
Change Title: Intel Desktop Board DG33TL, PCN 107716-01, Product Design, PATA/IDE controller change, Reason for Revision: PCN information updated
Date of Publication: July 26, 2007

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 10, 2007
---	--------------

Description of Change to the Customer:

Reason for Revision: PCN information updated

Parallel ATA/IDE controller change to Marvell 88SE6101 controller to improve usability. The new controller will not require F6 floppy driver for Windows XP operating system installation if installing to an attached PATA/IDE optical or hard disk drive.

Customer Impact of Change and Recommended Action:

The PATA/IDE controller change will impact existing operating system image. Customers with OS image built with previous PATA/IDE controller may require a reboot to complete driver re-enumeration. Intel recommend customers to perform re-qualification of the OS image.

The changes have been thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Post Change AA
BLKDG33TLM 890277	890277	D89517-700	D89517-801
BOXDG33TLM 890280	890280	D89517-700	D89517-801

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

July 6, 2007

00

Originally Published PCN

July 26, 2007

01

PCN information updated