



Product Change Notification

107949 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107949 - 01
Change Title: Intel(r) Server System S7000FC4UR Power Supply Spare, PCN 107949-01, Product Design, CLASS 2 POWER SUPPLY UPDATE TO SPARE, Reason for Revision: PCN 107949-00 had listed some previous changes due to internal communication errors.
Date of Publication: October 02, 2007

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 28, 2007
---	--------------

Description of Change to the Customer:

Reason for Revision: PCN 107949-00 had listed some previous changes due to internal communication errors.

The power supply is changing from part number D60079-005 to D60079-008. Changes include:

- * Minor component changes to improve PSU quality and manufacturability.
- * Added CE and C-tick marks to PSU label.
- * Updated label and FRU part numbers from -005 to -008.
- * Power supply firmware revised to resolve a false thermal indication which prevented the PSU from operating.

Customer Impact of Change and Recommended Action:

The power supplies are interchangeable. Intel anticipates no impact to customers.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change Product Code	Post Change MM#	Post Change TA
AFC4UPWR	891016	E10460-001	AFC4UPWR	891016	E10460-002

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

September 25, 2007

October 2, 2007

Revision Number:

00

01

Reason:

Originally Published PCN

PCN 107949-00 had listed some previous changes due to internal communication errors.