



Product Change Notification

108397 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108397 - 02
Change Title: Intel(r) Server System S7000FC4UR, PCN 108397-02, Product Design, CLASS 2, Power Distribution Board and Hot Swap Backplane Update, Reason for Revision: SFC4URE is being decoupled from this PCN and added to PCN 108517-00
Date of Publication: May 22, 2008

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	May 22, 2008
---	--------------

Description of Change to the Customer:

Reason for Revision: SFC4URE is being decoupled from this PCN and added to PCN 108517-00

Hotswap Backplane Firmware updated to correct HSC Fault LED and Locate feature. Change the 30 pin Tyco connector on PDB from RoHS 5 to RoHS 6 compliance.

SFC4UR
MM #891429 revs to 07
TA #E10476-005 rolls to -006 Rev 02
PBA Hotswap Backplane D55016-203 rolls to -204
PBA Power Distribution Board C90042-351 rolls to -352

Customer Impact of Change and Recommended Action:

Server Boards and Platforms, Product Design, Customers may want to perform re-qualification, re-test, re-certification or standard validation testing for this change.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change Product Code	Post Change MM#	Post Change TA
SFC4UR	891429	E10465-005	SFC4UR	891429	E10465--006

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

April 13, 2008

00

Originally Published PCN

May 12, 2008

01

TA correction for SKU SFC4UR

May 22, 2008

02

SFC4URE is being decoupled from
this PCN and added to PCN
108517-00