



Product Change Notification

103594 - 02

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2003. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash, Trillium is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 103594 - 02
Change Title: SE7501WV2, PCN 103594-02, FYI, Class 2;
Board Changes - Current BMC Flash and
BIOS Flash Parts going End of Life
Date of Publication: November 21, 2003

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Product Material

Forecasted Key Milestones:

	Board SKU's available date	System SKU's available date
Date of First Availability of Post-Conversion Material:	Nov 07, 2003	Dec 19, 2003

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

BMC Flash part at location U3B4; part number C14186-001 is going end of life and will be replaced with part number C47999-001.
BIOS Flash parts at location U1H1; part number A88862-001 is going end of life and will be replaced with part number A88862-003.

Customer Impact of Change and Recommended Action:

BMC Flash part at location U3B4; part number C14186-001 is going end of life and will be replaced with part number C47999-001 - Customer needs to be aware of the change; no impact to customer expected.
BIOS Flash parts at location U1H1; part number A88862-001 is going end of life and will be replaced with part number A88862-003 - Customer needs to be aware of the change; no impact to customer expected.

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SE7501WV2SKU02	855630	855630	C22264-012	C22264-013	A99386-110	A99386-111

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SWV1USKU07	853491	853491	C32003-006	C32003-007	A99386-110	A99386-111
SWV2USKU07	853492	853492	C32002-007	C32002-008	A99386-110	A99386-111
SE7501WV2S02NA	852233	852233	C22264-011	C22264-012	A99386-110	A99386-111

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BWV533ABB	852293	852293	C24243-110	C24243-111	A99388-110	A99388-111
BWV533SBB	854546	854546	C12319-110	C12319-111	A99388-110	A99388-111
SE7501WV2ATA	851374	851374	C12309-003	C12309-004	A99388-110	A99388-111
SE7501WV2SCSI	851370	851370	C12308-003	C12308-004	A99388-110	A99388-111

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

September 30, 2003

00

Originally Published PCN

October 1, 2003

01

Implementation date change TA Corrections

November 21, 2003

02

Update ECO implementation date for system SKU's. Update TA information.