



Product Change Notification

105993 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105993 - 00
Change Title: BHWBASE, PCN 105993-00,
Product Material,
CLASS 1: BIOS update, PLD code update,
AND gate change on Fibre Channel slot
Date of Publication: February 28, 2006

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 17, 2006
---	--------------

Description of Change to the Customer:

BHWBASE

Change the MM# from 875336 to 877488

Change top assembly part number from C95272-603 to C95272-604

Change main board part number from C51891-603 to C51891-604

Change the BIOS to P06

Change PLD2 to version 4.2

Change AND Gate for PCIx_RST on the Fibre Channel Module slot

CHANGE BIOS TO P06:

BIOS update supports Intel® Xeon® Processor 7000 sequence.

CHANGE PLD2 TO 4.2:

Change to processor throttling setting when a power supply is not connected to AC power.

FIBRE CHANNEL MODULE SLOT:

Adjustment to the fibre channel module slot reset to improve tolerance.

Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

Products Affected / Intel Ordering Codes:

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
BHWBASE	875336	877488	C95272-603	C95272-604	C51891-603	C51891-604

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

February 28, 2006

Revision Number:

00

Reason:

Originally Published PCN