



Product Change Notification

104665 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 104665 - 00
Change Title: SR1400 & SR2400 Fixed Drive Kit, FYI,
Class 2: CDROM Interposer Card Assembly
Change
Date of Publication: December 17, 2004

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 03, 2005
---	--------------

Description of Change to the Customer:

A design change was made to the spacer used between with CDROM drive and CDROM interposer card. The Interposer assembly numbers are changing from:

C74968-301 TO C74968-302.

This design change was made to address an issue with the CDROM tray "Sticking" when ejected. With this design change, both screws can now be used to attach the interposer assembly to the CDROM drive. See Technical Advisory #0739 for issue details.

Customer Impact of Change and Recommended Action:

Intel anticipates little to no impact to customers. Evaluate when available

Products Affected / Intel Ordering Codes:

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
AFIXDRVKIT	857208	857208	C56016-001	C56016-002	See Change Details	See Change Details

PCN Revision History:

Date of Revision: December 17, 2004	Revision Number: 00	Reason: Originally Published PCN
---	-------------------------------	--

