



Product Change Notification

103985 - 01

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash, Trillium is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 103985 - 01
Change Title: SR1300, PCN 103985-00, FYI, Class 2; 1U Bezel Change
Date of Publication: March 25, 2004

Type of Change Notification:
FYI - (For Your Information)


Key Characteristics of the Change:
Product Material

Forecasted Key Milestones:


Date Customer Must be Ready to Receive Post-Conversion Material:	Apr 23, 2004
---	--------------

Description of Change to the Customer:

Adding a notch in the inside of the bezel for clearance to the floppy drive eject button for use in future server products. See drawing below for details:



Notch in bezel required for clearance to floppy drive ejector button.



Customer Impact of Change and Recommended Action:

Adding a notch in the inside of the bezel for clearance to the floppy drive eject button for use in future server products - Customer needs to be aware of the change.

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SWV1USKU07	853491	853491	C32003-007	C32003-007	C32198-001	C32198-002

Component Product Table

Pre-Conversion Product Code	Pre-Conversion Spec/ROM	Pre-Conversion MM#	Post-Conversion Product Code	Post-Conversion Spec/ROM	Post-Conversion MM#
ACWBEZBLACK	A88522-001	847518		A88522-002	847518
ACWBEZSKU07	C32349-001	853489		C32349-001	853489

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

March 25, 2004

00

Originally Published PCN

March 25, 2004

01

Corrected Spelling Error