



# Product Change Notification

## 105839 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at  
<http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 105839 - 02  
**Change Title:** D945GCZ, PCN 105839-02, Product Design, Bios update, Reason for Revision: Change to NT94510J.86A.3528  
**Date of Publication:** February 13, 2006

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Mar 02, 2006
---	--------------

## Description of Change to the Customer:

### Reason for Revision: Change to NT94510J.86A.3528

Update bios to version NT94510J.86A.3528. Please refer to the release notes at <http://www.intel.com/products/motherboard/d945gcz> for details on the changes.

## Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. UPSD is not recommending additional qualification of these changes on platforms received from Intel. These board changes are expected not to cause a change to the Microsoft\* Windows\* operating system's software driver stack.

## Products Affected / Intel Ordering Codes:

### Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BLKD945GCZL	869574	869574	C99368-501	C99368-502	C99370-501	C99370-502
BLKD945GCZLKR	869570	869570	C99567-502	C99567-503	C99568-502	C99568-503
BLKD945GCZLR	869576	869576	D10312-502	D10312-503	D10313-502	D10313-503
BOXD945GCZL	869573	869573	C99368-501	C99368-502	C99370-501	C99370-502
BOXD945GCZLKR	869569	869569	C99567-502	C99567-503	C99568-502	C99568-503
BOXD945GCZLR	869579	869579	D10312-502	D10312-503	D10313-502	D10313-503
LAD945GCZCS	869689	869689	D10307-502	D10307-503	D10310-502	D10310-503

<b>Affected Product Code</b>	<b>Pre-Change MM#</b>	<b>Post-Change MM#</b>	<b>Pre-Change TA or AA</b>	<b>Post-Change TA or AA</b>	<b>Pre-Change PBA</b>	<b>Post-Change PBA</b>
LAD945GCZLK	868926	868926	D10253-500	D10253-501	D10254-500	D10254-501
LAD945GCZLKR	868924	868924	C99567-502	C99567-503	C99568-502	C99568-503

### **Reference Documents / Attachments:**

**Document:**

**Location #:**

### **PCN Revision History:**

**Date of Revision:**

**Revision Number:**

**Reason:**

January 18, 2006

00

Originally Published PCN

January 20, 2006

01

Wrong bios version

February 13, 2006

02

Change to NT94510J.86A.3528