



Product Change Notification

104816 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 104816 - 02
Change Title: SE7221BA1-E, Class1, PCN 104816-02, FFF, Replacement of board FAB from C833989-203 to C83389-301
Date of Publication: April 14, 2005

Type of Change Notification:
FFF - (Form-Fit-Function)

Key Characteristics of the Change:
Product Material

Forecasted Key Milestones:

| | |
|--|--------------|
| Date of First Availability of Post-Conversion Material: | Mar 18, 2005 |
|--|--------------|

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

The Intel Entry Server Board SE7221BA1-E FAB is upgraded with the following changes:

Chassis intrusion two pin header added, chassis intrusion inverter added to correct switch position, added I2C header, added (empty) front four pin fan header and changed pullup resistor value to increase brightness of front panel power LED.

The SSI connector silkscreen is being revised to match the Technical Product Specification document.

Note: The board AA number was incorrectly published in the PCN, the AA number is C83389-301, the updates to the product remain the same as previously listed.

Customer Impact of Change and Recommended Action:

Evaluate when received, customer changes are not required.

Products Affected / Intel Ordering Codes:

Board Products Table

| Affected Product Code | Pre-Change MM# | Post-Change MM# | Pre-Change TA or AA | Post-Change TA or AA | Pre-Change PBA | Post-Change PBA |
|-----------------------|----------------|-----------------|---------------------|----------------------|----------------|-----------------|
| SE7221BA1 | 868624 | 868624 | C83389-203 | C83389-301 | C83389-203 | C83389-301 |

| Affected Product Code | Pre-Change MM# | Post-Change MM# | Pre-Change TA or AA | Post-Change TA or AA | Pre-Change PBA | Post-Change PBA |
|-----------------------|----------------|-----------------|---------------------|----------------------|----------------|-----------------|
| 868624 | | | | | | |

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

February 10, 2005

00

Originally Published PCN

March 7, 2005

01

updating PCN with Silkscreen changes to board FAB

April 14, 2005

02

The factory changed the board number to C83389-301. All of the changes remain the same as the - 300 board.