



Product Change Notification

105925 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANdesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105925 - 00
Change Title: SE7520AF2, PCN 105925-00, Product Design,
CLASS 2, ALIEF SAK UPDATE,
RESOURCE CD AND ISM CD TO 8.4,
ROLL IN NEW INSULATOR
Date of Publication: February 15, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 17, 2006
---	--------------

Description of Change to the Customer:

Update SAK with new Resource CD (with FRUSDR 6.6.4 and ISM CD 8.4).
ROLL IN NEW INSULATOR TO PBAs.

Customer Impact of Change and Recommended Action:

None.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BAF2BB	871305	871305	C52145-703	C52145-704	C48105-703	C48105-704
BAF2HPBB	871303	871303	C52143-704	C52143-705	C47886-704	C47886-705
BAF2NSBB	871308	871308	C81871-703	C81871-704	C80508-703	C80508-704
SC47886	873650	873650	C90084-704	C90084-705	C47886-704	C47886-705
SC48105	876284	876284	C93755-703	C93755-704	C48105-703	C48105-704
SE7520AF2	871306	871306	C95591-006	C95591-007	C48105-703	C48105-707

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision: February 15, 2006	Revision Number: 00	Reason: Originally Published PCN
---	-------------------------------	--

