



# Product Change Notification

## 107090 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 107090 - 00  
**Change Title:** D945CZ, PCN 107090-00, Product Design, Product improvement  
**Date of Publication:** December 11, 2006

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Dec 29, 2006
-------------------------------------------------------------------------	--------------

## Description of Change to the Customer:

Product improvement for skus with LAN subsystem using the Intel® 82573E/82573V/82574V Gigabit Ethernet Controller.

## Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. UPSD is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft\* Windows\* operating system's software driver stack. No expected OS image change.

## Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Pre Change PBA	Post Change AA	Post Change PBA
LAD945GCZLKR 868924	868924	C99567-505	C99568-505	C99567-506	C99568-506
LAD945GCZLK 868926	868926	D10253-502	D10254-503	D10253-503	D10254-503
BOXD945GCZLKR 869569	869569	C99567-505	C99568-505	C99567-506	C99568-506
BLKD945GCZLKR 869570	869570	C99567-505	C99568-505	C99567-506	C99568-506
LAD945GCZCS 869689	869689	D10307-505	D10310-505	D10307-506	D10310-506

## Reference Documents / Attachments:

**Document:** **Location #:**

**PCN Revision History:**

**Date of Revision:**

December 11, 2006

**Revision Number:**

00

**Reason:**

Originally Published PCN