



Product Change Notification

107734 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107734 - 00

Change Title: D945GNT, PCN 107734-00,
Product Design, BIOS Update

Date of Publication: July 18, 2007

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 16, 2007
---	--------------

Description of Change to the Customer:

Intel Desktop Board D945GNT will be updated with latest BIOS

Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. Intel is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. No expected OS image change.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Pre Change PBA	Post Change AA	Post Change PBA
LAD945GNTL 868958	868958	C96315-408	C96317-408	C96315-409	C96317-409
BLKD945GNTL 869551	869551	C96315-408	C96317-408	C96315-409	C96317-409
BOXD945GNTL 869552	869552	C96315-408	C96317-408	C96315-409	C96317-409
BLKD945GNTLKR 869553	869553	C96320-406	C96322-406	C96320-407	C96322-407
BOXD945GNTLKR 869558	869558	C96320-406	C96322-406	C96320-407	C96322-407
BOXD945GNTLR 869796	869796	C96324-405	C96326-405	C96324-406	C96326-406
BLKD945GNTLR 869797	869797	C96324-405	C96326-405	C96324-406	C96326-406

OEMD945GNTLKRDB888130	888130	D82815-403	D82816-403	D82815-404	D82816-404
-----------------------	--------	------------	------------	------------	------------

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision: July 18, 2007	Revision Number: 00	Reason: Originally Published PCN
---	-------------------------------	--