



# Product Change Notification

## 106807 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 106807 - 00  
**Change Title:** Intel Dialogic® DI0408LSAR2I and DIINTPPS, PCN 106807-00, Product Discontinuance, Product Discontinuance there are no plans to generate RoHS versions of these products  
**Date of Publication:** October 12, 2006

## Key Characteristics of the Change:

Product Discontinuance

## Forecasted Key Milestones:

<b>Orders are Non-Cancelable and Non-Returnable After:</b>	Jun 25, 2007
<b>Last Product Discontinuance Order Date:</b>	Aug 25, 2007
<b>Last Product Discontinuance Shipment Date:</b>	Nov 17, 2007
<b>Last Product Return Date:</b>	Jun 02, 2007
<b>Technical Support Service Ends:</b>	Aug 25, 2008

## Description of Change to the Customer:

Discontinuance of Intel Dialogic® DI0408LSAR2I board and DIINTPPS Power supply. Products are being discontinued because there are no plans to generate RoHS versions of these products. Specific Product Codes being retired are listed below.

## Customer Impact of Change and Recommended Action:

Please determine your remaining demand for the affected products and place orders in accordance with the key milestones listed.

These products will no longer be supported after August 25, 2008. End of Support is defined as the date after which the following support services are no longer available:

- Software availability - download and ordering
- Telephone, email and web support for affected product(s)
  - Customers will be directed to migration product
- Active reproduction of customer-reported issues
- Installation and configuration support
- Technote and application note creation and maintenance
- Issue entry and tracking via issue management tool
- Defect entry. Fixes for unresolved defects will not be pursued nor released in Point or Service Packages, or in a product revision.
- No new Feature Requests will be accepted.

The End of Support date does not impact the terms of any stated hardware product warranty that governs product repair service.

**Migration Plan**

<b>Product Names</b>	<b>MM#</b>	<b>Migration Product</b>	<b>MM#</b>	<b>Notes</b>
DI0408LSAR2I	858547	DI0408LSW	884440	Customers need to move to MSISCGBLPOWMODW for powering stations
DIINTPPS	852110	Up to three MSISCGBLPWRMODW	882818	One MSISCGBLPWRMODW will be needed for each DI0408LSW board
DI0408LSAR2JPI	858548	N/A	N/A	Not creating a new RoHS DI0408LS (non-I) board for JP due to no sales
DI0408LSAR2EUI	858549	DI0408LSWEU	884424	Customers need to move to MSISCGBLPOWMODW for powering stations

Contact your sales representative for migration information and/or any issues you may have with this Product Discontinuance Plan.

**Products Affected / Intel Ordering Codes:**

<b>Product Code</b>	<b>MM#</b>
DIINTPPS	852110
DI0408LSAR2I	858547
DI0408LSAR2JPI	858548
DI0408LSAR2EUI	858549

**Reference Documents / Attachments:**

**Document:** \_\_\_\_\_ **Location #:** \_\_\_\_\_

**PCN Revision History:**

<b>Date of Revision:</b>	<b>Revision Number:</b>	<b>Reason:</b>
October 12, 2006	00	Originally Published PCN