



Product Change Notification

106524 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106524 - 01
Change Title: SR4850HW4/M, SR6850HW4/M,
SHW4URM3SA and SHW6URM3SA,
PCN 106524-01, Product Material,
Class 2: Remove burrs from DVD drive
bracket,
**Reason for Revision: Top Assembly will not
change.**
Add Servers SHW4URM3SA and
SHW6URM3SA.
Date of Publication: August 07, 2006

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 11, 2006
---	--------------

Description of Change to the Customer:

Reason for Revision: Top Assembly will not change. Add servers SHW4URM3SA and SHW6URM3SA.

A tooling change has been made to remove burrs from the DVD drive bracket.

SR4850HW4/M

877222

Change the chassis assembly part number from C54427-010 to C54427-011

Change the bracket assembly from C58601-006 to C58601-007

Change the DVD bracket from C58602-005 to C58602-006

SHW4URM3SA

881586

Change the chassis assembly part number from C54427-010 to C54427-011

Change the bracket assembly from C58601-006 to C58601-007

Change the DVD bracket from C58602-005 to C58602-006

SR6850HW4/M
877219

Change the chassis assembly part number from C69408-007 to C69408-008
Change the bracket assembly from C58601-006 to C58601-007
Change the DVD bracket from C58602-005 to C58602-006

SHW6URM3SA
881402

Change the chassis assembly part number from C69408-007 to C69408-008
Change the bracket assembly from C58601-006 to C58601-007
Change the DVD bracket from C58602-005 to C58602-006

Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SHW4URM	877222	877222			C58602-005	C58602-006
SHW4URM3SA	881586	881586			C58602-005	C58602-006
SHW6URM	877219	877219			C58602-005	C58602-006
SHW6URM3SA	881402	881404			C58602-005	C58602-006

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

July 12, 2006

00

Originally Published PCN

August 7, 2006

01

Top Assembly will not change. Add servers SHW4URM3SA and SHW6URM3SA.